

Trace600
OTDR Test Management Software
User's guide

Trace600
OTDR Test Management Software
User's guide



Contents

Section 1: General Information

Introduction	1
Contacting Noyes Customer Service	1
System Requirements	2
Installing Trace600	2

Section 2: Trace600 Screens and Menus

Main Screen	5
Menu Bar	8
File Menu	8
Events Menu	10
View Menu	12
Toolbar	14
Trace Graph Window	16
Event Table Window	18
Keyboard Shortcuts.....	20

Section 3: Transferring Trace Files to a PC

Traces Saved with M600 or M100 OTDR	21
Transferring Traces	21
Removing CompactFlash™ Memory Card	22

Disconnecting ImageMate USB Reader/Writer	22
Traces Saved with OFL 200 OTDR.....	23
OFL 200 File Transfer Dialog Box	23
Transferring Traces	26

Section 4: Managing Trace Files

Single Trace or Trace Pair?	28
Opening Trace Files.....	29
Opening a Single Trace	29
Opening a Trace Pair	30
Opening Previous or Next Traces	31
Comparing Traces with a Baseline Trace	31
Closing Files with Changes	33

Section 5: Analyzing Traces

Moving Cursors and Zooming	34
Selecting the Active Cursor	34
Moving the Active Cursor	35
Zoom In and Out of a Trace	35
Un-zoom and Re-zoom the Trace Display	36
Selecting Loss Method	37
Positioning Cursors Correctly	38
Two Point Loss Method	38

Single Event Loss Method	39
Multiple Event Loss Method	40
Fiber Attenuation Loss Method	41
Start (No Launch Cable) Loss Method	42
End (No Receive Cable) Loss Method	43
Adjusting LSA Lines	44
Adding Manual Events	45
Editing Comments.....	46
Deleting Events	47
Editing Trace Information.....	48
Editing a Single Trace	48
Batch Editing	50

Section 6: Printing Trace Reports

Selecting a Printer.....	54
Printing a Single Trace Report.....	55
Printing Multiple Trace Reports - Batch Printing.....	56
Batch Print Dialog Box	56
Selecting Traces for Batch Print.....	58
Creating a Cover Page for your Batch Print Job	60

Section 1: General Information

Introduction

Trace600 is a Windows®-based application designed to view, analyze, edit, and print trace files saved with M600 Mini-OTDR, M100 Handheld OTDR, and OFL 200 Handheld OTDR.

Note: Trace600 is not licensed software; you are free to copy it as needed. Please check our web site at www.AFLtele.com (**click on Products >Noyes Test & Inspection > Software**) for software updates and additional application information.

This User's guide contains detailed information about Trace600 tools and commands and assumes you have a working knowledge of your computer and standard Windows menus & commands. For help with any of these techniques, please see your Windows documentation.

If you have any questions about your OTDR and Trace600 software, or if you need technical or sales support, please contact Noyes Customer Service.

Contacting Noyes Customer Service

You may call Noyes Customer Service between 8 a.m. and 5 p.m., United States Eastern Time, as follows:

Phone: 800-321-5298 (North America)
603-528-7780

Fax: 603-528-2025

Web: www.AFLtele.com (click on Products > Noyes Test & Inspection)

System Requirements

To use Trace600 application, you need the following hardware and software:

- A 400 MHz (or faster) personal computer or laptop with an 800 x 600 (or larger) display
- A CD-ROM drive
- At least 32 megabytes (MB) of RAM
- A Windows compatible pointing device (mouse, trackball, etc.)
- MS Windows 9X, 2000, XP, or NT 4.0

Installing Trace600

You can install Trace600 from the supplied CD-ROM, or you can download it from our web site at **www.AFLtele.com** (click on **Products > Noyes Test & Inspection > Software**).

If you have an old version of Trace600, uninstall it first. Follow the steps below to install the Trace600 software.

To install from the application CD-ROM:

- 1 Start Windows®. If Windows is running, quit all applications.
- 2 Insert the Trace600 CD into the CD-ROM drive. (Note: normally the D: drive.)
- 3 The InstallShield® Wizard will display the [Welcome] screen.

Note: If the InstallShield Wizard does not start automatically, from Windows do one of the following:

- - Click on the [Start] button and select the [Run] command from the pop-up menu.
 - The [Run] dialog box appears. On the [Open] command line, type [D:\setup.exe].
 - Click on the [OK] button to start.

OR

- - Double-click the My Computer icon on the desktop to open the My computer folder.
 - Double-click the CD-ROM icon.
 - Double-click [Setup.exe] in the T600v2 folder.
- 4 When the InstallShield® Wizard [Welcome] screen is displayed, click on the [Next] button to continue.
 - 5 Follow the on-screen instructions.
 - 6 When the InstallShield Wizard displays the [Complete] screen, click on the [Finish] button.

To download from the web:

- 1 From the **www.AFLtele.com** web site, select the following:
Products > Noyes Test & Inspection > Software > Trace 600 PC Software > click on the download icon.
- 2 Follow the on-screen instructions. The software will download to your computer's hard drive.
- 3 Once downloaded, double-click on the [T600v2.exe] file.

- 4 When the InstallShield® Wizard [Welcome] screen is displayed, click on the [Next] button to continue.
- 5 Follow the on-screen instructions.
- 6 When the InstallShield Wizard displays the [Complete] screen, click on the [Finish] button.

Starting Trace600

Follow the steps below to start the Trace600 application:

- 1 In Windows, click on the [Start] button.
- 2 From the [Start] pop-up menu, select the [Programs] menu.
- 3 Locate the Noyes Fiber Systems folder.
- 4 Click on the Trace600 shortcut.

If you have installed the Trace600 application in a folder other than Noyes Fiber Systems, choose that folder from the Start > Programs menu.

Note: To see filename extensions that show fiber type and wavelength (m85, m13, s13, s15, m85.sor, m13.sor, s13.sor, s15.sor) when browsing for trace files, perform the following steps:

- 1 From Windows (not Trace600), open the folder containing trace files.
- 2 Open the [View] dialog box by clicking on Tools > Folder Options > View.
- 3 In the [Advanced Settings] window, remove the check next to the [Hide file extensions for known file types] option.
- 4 Repeat steps 1- 3 for other folders containing trace files.

Section 2: Trace600 Screens and Menus

This section provides an overview of key features of the Trace600 software.

Main Screen

The Trace600 main screen is divided into several sections. Each section contains a specific type of information (refer to Figure 2-1). The table below gives a summary of the [Main] screen features.

Ref #	Feature	Description
1	Menu bar	Displays the available pull down menus.
2	Toolbar	Contains several icons for quick access to menu commands. Click on an icon to execute the related command.
3	Zoom window	Shows the size of the current view and the location of cursors relative to the entire trace.
4	Cursor data	This section displays the following information: A and B cursor locations, distance from A to B, selected loss method, plus (depending on the selected loss method) insertion loss, event level data, and reflectance.
5	OTDR/Text data	This section displays OTDR setup parameters or Text data when the corresponded tab [OTDR info] or [Text info] is selected.




Figure 2-1: Trace600 Main Screen.

6	[OTDR Info] tab	Click on this tab to display OTDR setup parameters stored in the selected trace file.
7	[Text Info] tab	Click on this tab to display text information stored in the selected trace file.
8	[Edit Trace Info] button	Click on this button to display the [Edit Trace Information] screen, which allows editing.
9	Vertical split bar	This bar allows resizing of the [Trace graph] and [Event table] window vertically. Drag the Vertical bar to the left or right to decrease or increase the [Trace graph] and [Event table] window.
10	Horizontal split bar	This bar allows resizing of the [Trace graph] and [Event table] window horizontally. Drag the Horizontal bar up or down to increase or decrease the [Trace graph] and [Event table] window.
11	[Event table] window	Displays saved events in a table format.
12	[Trace graph] window	Shows a graph of the currently selected trace. Up to four traces can be displayed in the [Trace graph] window.
13	Currently selected trace tab	If several trace files are opened, click a trace tab to display the desired trace graph.

File Events View Help	
Open Trace...	Ctrl+O
Open Baseline...	Ctrl+B
Next File	Ctrl+N
Prev File	Ctrl+P
Close	Ctrl+F4
Save	Ctrl+S
Save As...	
Print...	
Printer Setup...	
Batch Print...	
Edit Trace Info...	
Batch Edit...	
Transfer Files from OFL 200...	
Exit	
1 C:\OFL 200\Trace_004_S15.sor	

Menu Bar

The Menu Bar located at the top of the Trace600 Main Screen (see Figure 2-1) displays the available pull down menus. Each menu contains various commands. When a menu is selected, it displays a list of commands indicating a task associated with each command.

File Menu


You can find all the commands you need to open, save, print, edit, and close trace files on the File pull down menu. The table below gives a summary of the available File Menu commands and associated functions.

Command		Function
Open Trace	Ctrl+O	Depending on the selected option (Single-wavelength or Dual-wavelength), open a single trace file or a trace file pair.
Open Baseline	Ctrl+B	Depending on the selected option (Single-wavelength or Dual-wavelength), open a single trace file or a trace file pair as a baseline.

Command	Function
Next File Ctrl+N	Open the next (alphabetically) file or pair in the current folder.
Prev File Ctrl+P	Open the previous (alphabetically) file or pair in the current folder.
Close Ctrl+F4	Depending on the selected option for closing files, close selected files after automatically saving changes, or prompt the user to confirm saving.
Save Ctrl+S	Save a trace file that already exists with its original name.
Save As	Save an existing trace file under a new name and preserve the original file.
Print	Print the currently displayed trace.
Printer Setup	Select a printer and set up printing options.
Batch Print	Allows printing of all or selected trace files in the current folder.
Edit Trace Info	Allows editing of trace text information and certain setup parameters.
Batch Edit	Use to edit text or set up field(s) in multiple traces.
Transfer files from OFL 200	Allows transferring files saved with an OFL 200 OTDR to a PC.
Exit	Close opened trace files and exit Trace600.

Events Menu

The Events pull down menu contains all the commands you will need to select loss methods, add new events, and review or delete saved events.




The table below gives a summary of the available Events menu commands and associated functions.

Command	Function
Add Event Ctrl+A	Add an event using the selected Loss Method at the current cursor location.
Loss Method	For analyzing traces and adding events, Trace600 offers various Loss Measurement Methods.
Current Event: <ul style="list-style-type: none"> • Edit Comment • Delete 	Open a dialog box for adding and/or editing comments for the current event. The maximum comment length is 94 characters. Delete the current event.
Next Event (Down Arrow)	Display the next event.
Prev Event (Up Arrow)	Display the previous event.
Delete All Events Shift+Del	Delete all saved events in the selected trace.
Restore Event Shift+Insert	Restore the last event that was deleted.
Restore LSA Defaults	Restore LSA line lengths to the default values.

View Menu

The View pull down menu contains all the commands you will need to magnify or reduce the display of any area in the [Trace graph] window, switch the active cursor, turn the Toolbar text on/off, and set up options. The table below gives a summary of the available View menu commands and associated functions.



Command	Function
Zoom in Horizontally (Shift+Up Arrow)	Magnify or reduce the display of any area in the [Trace graph] window.
Zoom out Horizontally (Shift+Down Arrow)	
Zoom In Vertically (Ctrl+Up Arrow)	
Zoom out Vertically (Ctrl+Down Arrow)	
Un-Zoom F6	
Re-Zoom F7	
A-B Cursor F4	Switch the active cursor.
Toolbar Text	Turn the Toolbar text on or off.
Options	Open the [Options] dialog box for specifying Trace600 options. See Fig. 2-2 for details.

Use the [Options] dialog box when you need to specify how to open and close trace files, how to close trace files with changes, and when you need to select distance units of measure.




Figure 2-2: Options Dialog Box.


Toolbar

Several of the most commonly used commands can be accessed from the Toolbar. Click on a toolbar icon to execute the corresponding command.



Open Trace...
Open Baseline...

Locate and open the desired trace file.



Save a trace file that already exists with its original name.



Print the displayed trace file.



Open the Edit Trace Information dialog box.




Open the previous file (trace file pair) in the current folder.



Open the next file (trace file pair) in the current folder.



Zoom in horizontally around the active cursor.



Zoom out horizontally around the active cursor.



Zoom in vertically from the trace level at the active cursor.



Zoom out vertically from the trace level at the active cursor.




Display the trace view at 100%.




Zoom to the previous zoom level around the active cursor.



Select the previous event.



Select the next event.



Switch the active cursor.

Trace Graph Window




Figure 2-3: Trace Graph Window.

The [Trace graph] window displays OTDR test results in a graph format. Up to four traces can be displayed in the [Trace graph] window. The major features of the [Trace graph] window are explained below.

Ref #	Feature	Description
1	Trace [Tab]	Displays the name and color of the open trace file. If several trace files are opened, click the desired trace [Tab] to display the trace graph.
2	Vertical axis	Shows Insertion loss in dB.
3	Horizontal axis	Shows distance in user-selected units.
4	Trace	This is a graph of insertion loss vs. distance.
5	Cursors A and B	Used to measure insertion loss, power level, reflectance, attenuation, and distance. To make a cursor active, click on the cursor line or label, or click on the Toolbar Cursor icon to toggle between A and B cursors. To move the active cursor, position the mouse pointer on a cursor, then click-and-drag along the trace graph. Also, you may use the Left and Right keyboard arrow keys.
6	Cursor label	To move the active cursor, position the mouse pointer on a cursor label, then click-and-drag along the trace graph.
7	Event mark	Indicates the location and number of a saved event. Events are ordered by the increasing location value.
8	LSA lines	Available for certain loss measurement methods. Used for calculating insertion loss, trace level, and attenuation.
9	LSA line boundaries	Near and Far LSA line boundaries for each LSA line segment. Used to control length and position (relative to trace segment) of LSA line.

Event Table Window

The [Event table] window allows you to view test data associated with the trace displayed in the [Trace graph] window. If several trace files are opened, click the desired trace [Tab] located on top of the [Trace graph] window to display the [Event table] of the desired trace. Using the [Events] menu, you may add or delete trace events and edit comments.

The screenshot shows the 'Event Table' window. Callout 1 points to the window title bar. Callouts 2 through 9 point to the columns of the table below.

Event Table							
▼ Number of Events: 4		Link Loss: 0.71 dB		Link Length: 803 m			
Fiber Before Event			Link Events				
	Atten.	Loss			Location	Refl.	Loss
#	(dB/km)	(dB)	Source	Type	m	(dB)	(dB)
1	---	---	Manual	Single Reflective	82.0	-47.86	0.05
2	0.70*	-0.07	Manual	Single Reflective	182.0	-40.43	-0.02
3	0.64*	-0.13	Manual	Single NonReflective	382.0	-80.31	0.16

Figure 2-4: Event Table Window.

Features of the [Event table] window are explained below.

Ref #	Feature	Description
1	Overall data	This row displays the overall trace data: number of saved events, link loss, and link length.
2	Event number	This column displays a sequential numbers of the saved events. Events in the [Event table] are ordered by their increasing location value.
3	Atten.(dB/km)	This column displays the lead-in fiber attenuation. The dB/km measurement is the slope of the fiber leading to the event Note: When the length of the fiber being measured is insufficient, the dB/km measurement is displayed followed by an asterisk [*] symbol. An asterisk [*] symbol indicates, "Section is too short to ensure an accurate fiber attenuation (dB/ km) measurement." The required minimum distance is dependant on wavelength: 1550 nm = 2630 m, 1310 nm = 1470 m, 1300 nm = 960 m, and 850 nm = 185 m.
4	Loss (dB)	This column displays the Insertion loss in (dB) of the fiber segment before the event.
5	Source	This column indicates how the events is added: <ul style="list-style-type: none">• manually - added by operator,• automatically - event table is generated by OTDR
6	Type	This column indicates the event type based on the selected loss method.

7	Location	This column displays the distance from OTDR to the event.
8	Refl. (dB)	Displays the Reflectance in (dB) for each reflective event
9	Loss (dB)	Displays the Insertion loss in (dB) for each event.

Keyboard Shortcuts

Available Trace600 keyboard shortcuts:

Open Trace...	Ctrl+O
Open Baseline...	Ctrl+B
Next File	Ctrl+N
Prev File	Ctrl+P
Close	Ctrl+F4
Save	Ctrl+S
Add Event	Ctrl+A
Next Event	Down Arrow
Prev Event	Up Arrow
Delete All Events	Shift+Del

Restore Event	Shift+Insert
Move Active Cursor	Left / Right Arrows
Zoom in Horizontally	(Shift+Up Arrow)
Zoom out Horizontally	(Shift+Down Arrow)
Zoom in Vertically	(Ctrl+Up Arrow)
Zoom out Vertically	(Ctrl+Down Arrow)
Un-Zoom	F6
Re-Zoom	F7
A-B Cursor	F4

Section 3: Transferring Trace Files to a PC

Traces Saved with M600 or M100 OTDR

Trace files saved with M600 or M100 OTDR are transferred to a PC using the supplied ImageMate™ USB 2.0 Reader/Writer and CompactFlash™ memory card.

Transferring Traces

To transfer trace files to a PC perform the following steps.

- 1 Connect the supplied ImageMate USB Reader/Writer to a USB 2.0 port on your PC while Windows® is running.
- 2 Windows will automatically recognize the ImageMate Reader/Writer and display it as [Removable Disk] in the [My Computer] folder.
- 3 Insert the CompactFlash card with saved test data in the ImageMate Reader/Writer.
- 4 Double-click on the [Removable Disk] icon to display saved trace files.
- 5 Using Windows commands, copy the desired trace files to your PC.

Important: To avoid data loss or malfunctions of your computer or ImageMate Reader/Writer, it is important to use Windows [Eject] and [Unplug] commands before physically removing CompactFlash™ memory card and ImageMate Reader/Writer. Refer to the following sections for details.

Removing CompactFlash™ Memory Card

Perform the following steps before removing a CompactFlash™ memory card from the ImageMate Reader/Writer:

- 1 Double-click on the [My Computer] icon to open the [My Computer] folder.
- 2 Right click on the [Removable Disk] icon.
- 3 From the pop-up menu, select the [Eject] command.
- 4 Pull the CompactFlash memory card out of the ImageMate USB Reader/Writer.

Disconnecting ImageMate USB Reader/Writer

You don't need to shut down your computer to disconnect the ImageMate USB Reader/ Writer, but you should never remove the device from the USB port without first reading the steps below. If a drive window is open, or the ImageMate Reader/ Writer is active, close any associated windows before attempting to remove the Reader/ Writer.

Use the [Add/Remove Hardware] command in Control Panel or [Safe to Remove Hardware] hotplug icon in the notification area of the taskbar to safely remove the ImageMate Reader/ Writer before unplugging. The notification area is to the right of the taskbar where you usually see the current time displayed.

- 1 In the notification area, right-click on the [Safe to Remove Hardware] hotplug icon.
- 2 Select the device you want to unplug, and then click [Stop].
- 3 When Windows notifies you that it is safe to do so, unplug the Reader/ Writer from your computer.

Traces Saved with OFL 200 OTDR

Trace files saved with an OFL 200 OTDR are transferred to a PC using the Trace600 software. Files selection and transfer are done in the [OFL 200 File Transfer] dialog box, which is accessed from the Trace600 [File] menu.

OFL 200 File Transfer Dialog Box

The [OFL 200 File Transfer] dialog box consists of several windows, numeric/text fields, and control buttons that allow you to perform the following tasks:

- Select all or multiple trace files for transferring to a PC.
- Remove all or multiple trace files from the transfer list.
- Rename trace files to be transferred.
- Renumber trace files to be transferred.
- Add information required for traces identification

The table below and Figure 3-1 describe the [OFL 200 File Transfer] dialog box features.

Ref #	Feature	Description
1	[OFL 200 Files] window	Displays a list of trace files saved with an OFL 200 OTDR. Note: If trace files are not displayed, select the appropriate Com Port, and then click on the [Refresh] button.
2	[Com Port] pull down list	Click on the [Down arrow] button at the end of the [Com Port] pull down list to display the available options.

3	[Refresh] button	After the appropriate Com Port is selected, click on this button to display a list of trace files in the [OFL 200 Files] window.
4	[Select All] button	Allows selecting all trace files displayed in the [OFL 200 Files] window. Note: To select or deselect files individually, click on the desired file name in the [OFL 200 Files] window.
5	[Select None] button	Allows deselecting all files.
6	[Transfer Files] button	Click on this button to start transferring.
7	[Close] button	Click on this button to close the [OFL 200 File Transfer] dialog box.
8	[Destination Files] window	This window displays the files as they will appear on the PC.
9	[Change Cable ID] check box	Check this box if you need to rename transferred trace files.
10	[Cable ID] text field	This is a text field where you enter a new name for transferred traces (if needed).
11	[Fiber Number] check box	Check this box if you need to renumber transferred trace files.
12	[Fiber Number] numeric field	This is a numeric field where you enter a starting number for transferred traces (if you need to renumber transferred traces).
13	Trace data text fields	This section contains text fields where you enter all information you need to identify a cable.




Figure 3-1: OFL 200 File Transfer Dialog Box.

Transferring Traces

To transfer trace files from the OFL 200 OTDR to your PC:

- 1 Turn the OFL 200 OTDR on.
- 2 Connect the OFL 200 to your PC using the supplied serial cable.
- 3 You should see the [Remote] soft key label on the OFL 200 display.

Press the [Remote] soft key on the OFL 200.

Note: On some computers the COM port will not turn on until step 5. In this case the [Remote] soft key will not be available until a warning message is displayed during step 5. Press the [Remote] soft key on the OFL 200 at that time. Please continue to step 4.


- 4 Open the Trace600 software.
- 5 From the Trace600 [File] menu, select the [Transfer files from OFL 200] command.

Note: You may experience several seconds delay until the [OFL 200 File Transfer] dialog box is displayed (see Figure 3-1).

- 6 From the displayed list, select the files to be transferred. Refer to the section titled “OFL 200 File Transfer Dialog Box” for details.
- 7 Click on the [Transfer Files] button to start.
- 8 The [Browse for Folder] screen will be displayed. Navigate to the desired destination, and then click on the [OK] button.
 - If needed, you may create a new folder by clicking on the [New folder] button.


Note: Occasionally the New Folder will not be editable after creating. If this happens, right-click on the New Folder icon and select the [Rename] command from the displayed pop-up menu.

9 While transfer is in progress, you will see the [Saving Files] screen.



- If needed, you may stop transferring at any time by clicking on the [Cancel] button.

10 When the transfer progress line indicates that files are saved on your PC, the [Cancel] button changes to [Done].



11 Click on the [Done], and then on the [Close] button.

Section 4: Managing Trace Files

Single Trace or Trace Pair?

Trace600 offers two options for opening and closing trace files. Depending on the selected option, a trace file or trace files in wavelength pairs (dual-wavelength trace file pair) may be opened and closed within the current folder.

If the Single-wavelength option is enabled, then trace files will be opened and closed one-at-a-time. If the Dual-wavelength option is enabled, then trace files will be opened and closed in wavelength pairs (files with the same name and fiber type but different wavelengths).

For example:


If a folder contains files named “FIBER001.M85” (multimode, 850 nm) and “FIBER001.M13 (multimode, 1300 nm)”, and in the file open dialog box the “FIBER001.M85” file is selected for opening, then Trace600 will automatically open both files. It doesn’t matter which file in a pair is selected first.

In addition to the current trace or pair, Trace600 allows you to open a baseline trace or pair for comparison with the current trace. If a dual trace pair and a dual baseline trace pair are opened, a total of four traces can be displayed at one time.

Opening Trace Files

Opening a Single Trace


- 1 From the [View] pull down menu, select the [Options] command to display the [Options] dialog box.



- 2 Select the [Single-wavelength] option, and then click on the [OK] button.
- 3 There are two ways to open a single trace file:
 - From the [File] pull down menu, select the [Open Trace] commandOR
 - Click the [Open] icon on the Toolbar
- 4 When the [Open Trace File] window is displayed, locate the drive and directory containing trace files.
- 5 From the displayed list of files, select the trace file you want to open.
- 6 Click on the [OK] button to open the file.

Opening a Trace Pair

- 1 From the [View] pull down menu, select the [Options] command to display the [Options] dialog box.



- 2 Select the [Dual-wavelength] option, and then click on the [OK] button.
- 3 There are two ways to open a trace pair:
 - From the [File] pull down menu, select the [Open Trace] commandOR
 - Click the [Open] icon on the Toolbar
- 4 When the [Open Trace File] window is displayed, locate the drive and directory containing trace files.
- 5 From the displayed list of files, select the trace file you want to open.
- 6 Click on the [OK] button to open the file.

Opening Previous or Next Traces

After you open a single trace or trace pair, you may use the [Prev File] and [Next File] commands to display the previous or following trace or trace pair in the current folder.

There are three ways to display the previous or following trace or trace pair:

- 1 From the [File] pull down menu, select the [Next File] or [Prev File] command.
- 2 Click the [Next File] or [Prev File] icon on the Toolbar.
- 3 Use the shortcuts: [Ctrl+N] - next trace; [Ctrl+P] - previous trace.

Comparing Traces with a Baseline Trace

Trace600 allows you to open a baseline trace or pair for comparison other traces with the current baseline trace or pair. If a dual baseline trace pair and a dual trace pair are opened, a total of four traces can be displayed at one time.

- 1 From the [View] pull down menu, select the [Options] command to display the [Options] dialog box. From this dialog box, select Single-wavelength (or Dual-wavelength) option, and then choose [OK].
- 2 From the [File] pull down menu, select the [Open Baseline] command.
 - When the [Open Trace File] window is displayed, locate the drive and directory containing trace files.
 - From the displayed list of files, select the trace file you want to open.
 - Click on the [OK] button to open the file.

- 3 From the [File] pull down menu, select the [Open Trace] command.
 - When the [Open Trace File] window is displayed, locate the drive and directory containing trace files.
 - From the displayed list of files, select the trace file you want to open.
 - Click on the [OK] button to open the file.
- 4 Click on the [Prev File] or [Next File] button to open the previous or following trace file or file pair in the current folder.

Note: The [Prev File] and [Next File] commands will not affect the baseline trace(s). You can open one trace (or trace pair) as a baseline trace and compare it to other traces in the current folder.


Closing Files with Changes

Two options are available for closing trace files with changes: [Save Automatically] and [Ask “Save Changes?”].

[Save Automatically] option	[Ask “Save changes?”] option
If a trace file has been edited and not saved, it will be saved automatically before closing.	If a trace file has been edited and not saved, a dialog box will appear prompting you to save changes before closing.

To specify how trace files will be closed perform the following steps.

- 1 From the [View] pull down menu, select the [Options] command to display the [Options] dialog box.



- 2 Select the desired option, then click on the [OK] button.

Section 5: Analyzing Traces

Moving Cursors and Zooming


The [A] and [B] cursors may be positioned to measure the insertion loss, power level (if applicable), reflectance (if applicable), attenuation (if applicable), and distance between any two points on a trace.

To make cursor positioning easier, Trace600 provides tools and commands for viewing different parts of a trace graph at various magnifications. [Zoom In] and [Zoom Out] commands let you magnify or reduce the display of any area in the [Trace graph] window.

Trace600 zooms horizontally around the active cursor and vertically from the trace level at the active cursor.

Selecting the Active Cursor

To make a cursor active, do one of the following:

- In the [Trace graph] window, click on the desired cursor line or label.
- From the Toolbar, click on the [Cursor] button  to toggle between cursors.
- From the [View] pull down menu, select the [A-B Cursor] command to toggle between cursors.
- Press the [F4] key on your keyboard to toggle between cursors.

Once the active cursor is selected, it can be moved along the trace graph.

Moving the Active Cursor

To move the active cursor, do one of the following:

- Position the mouse pointer on a cursor line or cursor label, then click-and-drag along the trace graph.
- Use the [Left] and [Right] keyboard arrow keys.

Note: The [A] cursor cannot be moved beyond the [B] cursor location, and vice versa.

Zoom In and Out of a Trace

You can magnify or reduce the trace display performing one of the following:

- From the Menu bar, select the [View] pull down menu, and then choose the desired Zoom command.



Zoom in horizontally around the active cursor.



Zoom out horizontally around the active cursor.



Zoom in vertically from the trace level at the active cursor.



Zoom out vertically from the trace level at the active cursor.

Note: Each click magnifies the view to the next preset percentage until the limit of magnification

is reached.

- From the Toolbar, click on the corresponding Zoom button

Zoom In Horizontally (Shift + Up Arrow)
Zoom Out Horizontally (Shift + Down Arrow)
Zoom In Vertically (Ctrl + Up Arrow)
Zoom Out Vertically (Ctrl + Down Arrow)

Un-zoom and Re-zoom the Trace Display

In the zoomed view, Trace600 always displays the active cursor area. The [Un-zoom] and [Re-zoom] commands allow you to display different areas of a trace graph at the same level of magnification. If you need to un-zoom, move the active cursor, and then re-zoom, Trace600 will display the new position of the active cursor at the previous zoom level.

Perform the following steps:

- 1 In the [Trace graph] window, use the [Zoom In] and [Zoom Out] commands to set the desired level of magnification.
- 2 Click on the [Un-zoom] button to display the trace view at 100%.
- 3 Relocate the active cursor as needed (or toggle between A and B cursors).
- 4 Click on the [Re-zoom] button to display the new cursor location at the previous zoom level.

Note: When you toggle between [A] and [B] cursors in the magnified view, the view changes accordingly to display area around the active cursor.

Selecting Loss Method

For analyzing traces and adding events, Trace600 offers various Loss methods. The following table gives a summary of the available methods.

Loss Method (and applications)	Measured parameters	# of cursors	# of LSA lines*
Two Point (general purpose)	Insertion loss between any 2 points of a trace	2	0
Single Event (used to analyze connections, splices, faults, etc.)	Location, Reflectance, Insertion loss of any Reflective or Non-Reflective event	1	2
Multiple Event (used if two or more events are too close to use other methods)	Location and Insertion loss of multiple events	2	2
Fiber Attenuation (used to measure dB/km of fiber between events)	Attenuation per km ratio of any segment of a trace with no events	2	2
Start - No Launch Cable (used to set start of fiber level)	Starting location and level of a trace	1	1
End - No Receive Cable (Used to set end of fiber level)	Location, Reflectance, and Trace level of the fiber end	1	1

*LSA Line - least squared approximation segment line. Used to reduce the effects of noise while calculating insertion loss, trace level, and attenuation.

To select the desired Loss method perform the following:


- 1 From the Menu bar, choose the [Events] pull down menu.
- 2 Choose the [Loss Method] command to display a list of the available options.
- 3 Select the desired Loss method.

Positioning Cursors Correctly

Depending on the selected Loss Method, you will need to position cursors and adjust LSA lines (if applicable) properly. The following graphs illustrate position of cursors and LSA lines for the available Loss methods.


Two Point Loss Method

- 1 Position the left cursor at the start of the event.
- 2 Position the right cursor beyond the event where the trace returns to a constant slope.
- 3 Read the insertion loss measurement displayed in the [Cursors data] window.




Single Event Loss Method

- 1 Position a cursor at the start of the event.
 - 2 If required, adjust the right LSA line so the Near Right boundary located beyond the event where the trace returns to a constant slope.
 - 3 Read the insertion loss measurement displayed in the [Cursors data] window.
- Or
- 4 From the [Events] pull down menu, choose the [Add Event] command to save.



Multiple Event Loss Method


- 1 Position the left cursor at the start of the first event.
 - 2 Position the right cursor at the start of the last event.
 - 3 If required, adjust the right LSA line so the Near Right boundary located beyond the event where the trace returns to a constant slope.
 - 4 Read the insertion loss measurement displayed in the [Cursors data] window.
- Or
- 5 From the [Events] pull down menu, choose the [Add Event] command to save.



Fiber Attenuation Loss Method


This method is used just for analyzing a trace.

- 1 Position left and right cursors on the trace as needed.
- 2 Read the insertion loss (dB/km) measurement displayed in the [Cursors data] window.




Start (No Launch Cable) Loss Method

- 1 Position the left cursor at the beginning of the trace (0 meters).
 - 2 If required, adjust the right LSA line so the Near Right boundary located beyond the reflection where the trace returns to a constant slope.
 - 3 Read the trace level measurement displayed in the [Cursors data] window.
- Or
- 4 From the [Events] pull down menu, choose the [Add Event] command to save.




End (No Receive Cable) Loss Method

- 1 Position the Left cursor at the start of the Far-end reflection.
 - 2 If required, adjust the left LSA line.
 - 3 Read the trace level measurement displayed in the [Cursors data] window.
- Or
- 4 From the [Events] pull down menu, choose the [Add Event] command to save.




Adjusting LSA Lines

If events of a trace are located very close to each other, you may have to adjust the LSA Lines. The graphs below illustrate an example of the right LSA line before and after the adjustment.



LSA Line before the adjustment



LSA Line after the adjustment

To adjust LSA lines, position the mouse pointer over an LSA line boundary, then click and drag to the desired location.

Note: if you need to restore the original LSA lines lengths values, choose the [Restore LSA Defaults] command from the [Events] pull down menu.

Adding Manual Events

To add manual events, perform the following steps:

- 1 From the [Events] pull down menu, select the [Add Event] command.
- 2 The [Add Event] dialog box opens displaying the event data that will be added to the [Event table] and allowing you to add a comment.
- 3 Type a comment in the Comment text field (maximum 94 characters) if needed.
- 4 Choose OK to save. Trace600 automatically places an event mark in the [Trace graph] window and event data in the [Event table] window.




Figure 5-1: Add Event Dialog Box.

Editing Comments

To edit a comment, do one of the following:

- 1 In the [Event Table], select the desired event by clicking on it.
 - From the [Events] pull down menu, select the [Current Event] to display the [Comments] submenu.
 - From the [Comments] submenu, select the [Edit comment] command to display the [Edit Event] dialog box (see Figure 5-1).
 - Edit comments as needed.
 - Click on the [OK] button to save changes.

OR

- 2 In the [Event Table], select the desired event by clicking on it.
 - Right-click the selected event, to display the [Comments] submenu.
 - From the [Comments] submenu, select the [Edit comment] command to display the [Edit Event] dialog box (see Figure 5-1).
 - Edit comments as needed.
 - Click on the [OK] button to save changes.

Deleting Events

To delete an event, do one of the following:

- 1 In the [Event table], select the desired event by clicking on it.
 - From the [Events] pull down menu, select the [Current Event] to display the [Comments] submenu.
 - From the [Comments] submenu, select the [Delete] command



OR

- 2 In the [Event table], select the desired event by clicking on it.
 - Right-click the selected event, to display the [Comments] submenu.
 - From the [Comments] submenu, select the [Delete] command

Editing Trace Information

Editing a Single Trace

Trace600 allows you to edit trace information and certain setup parameters. This is done in the [Edit Trace Information] dialog box.

- 1 There are three ways to display the [Edit Trace Information] dialog box.
 - From the [File] pull down menu, select the [Edit Trace Info] command.
 - From the Toolbar, click on the [Info]  button.
 - Click on the  button.
- 2 When the [Edit Trace Information] dialog box is displayed, edit text fields as needed.
- 3 Choose [OK] to save changes.

Refer to the following description and Figure 5-2 for details.

Ref #	[Edit Trace Info.] dialog box feature	Description
1	[Text Info] section	This section contains text fields where you enter all information you need to identify a trace.
2	Date field	Click on the [Down arrow] button at the end of the Date field to display a pop-up calendar and edit test date as needed.
2	Fiber number field	Allows you to change the fiber number.

4	Group index	Allows you to change the Group index value.
5	BackScatter coefficient	Allows you to change the BackScatter coefficient value.
6	Reflectance threshold	Allows you to change the Reflectance threshold value.




Figure 5-2: Edit Trace Information Dialog Box.

Batch Editing

The Batch editing feature allows you to edit all or selected test properties (such as fiber name, fiber number, test site data, and comments) in multiple trace files in the current folder. This is done in the [Batch Edit] dialog box. The [Batch Edit] dialog box consists of several windows and control buttons. The table below gives a summary of the [Batch Edit] dialog box features (see Figure 5-3).

Ref #	Feature	Description
1	[Drive] window	Allows you to navigate to the desired folder
2	[Files in Folder] window	Displays all trace files in the currently selected folder
3	[Files to Edit] window	Displays all trace files added to the batch edit list
4	[Add] button	Adds a single trace or multiple traces to the batch edit list
5	[Add All] button	Allows you to add all traces to the batch edit list
6	[Remove] button	Allows you to remove a single trace or multiple traces from the batch edit list
7	[Remove All] button	Allows you to remove all traces from the batch edit list
8	Properties check boxes	Select corresponding check boxes to activate editable text fields
9	Text editable fields	This section contains text fields where you enter all information you need to identify traces
10	[Clear all Text] button	Removes all text from the text fields section
11	[OK] button	Click on this button to complete changes
12	[Exit] button	Closes the [Batch Edit] dialog box




Figure 5-3: Batch Edit Dialog Box.

To edit all or selected files, perform the following:

- 1 From the [File] pull down menu, select the [Batch Edit] command to access the [Batch Edit] dialog box.
- 2 In the [Drive] window, locate and select the desired folder.
- 3 Double-click on the selected folder to open it.
- 4 All trace files in the open folder will be displayed in the [Files in Folder] window.
- 5 From the [Files in Folder] window, add the desired traces to the batch edit list, which will be displayed in the [Files to Edit] window. Use the [Add] or [Add All] buttons for adding trace files.

- To add trace files individually:

Double-click the desired trace name listed in the [Files in Folder] window. The trace name added to the batch edit list will appear in the [Files to Edit] window.

OR

Click on the desired trace name listed in the [Files in Folder] window, then click on the [Add] button. The trace name added to the batch edit list will appear in the [Files to Edit] window.

- To add all trace files in the current folder to the batch edit list, click on the [Add All] button. The added trace names will appear in the [Files to Edit] window.
- 6 If you need to remove trace files from the batch edit list displayed in the [Files to Edit] window,

use the [Remove] or [Remove All] buttons.

- To remove trace files from the batch edit list individually:

Double-click the desired trace name displayed in the [Files to Edit] window. The trace name listed in the [Files to Edit] window will be removed.

OR

Click on the desired trace name displayed in the [Files to Edit] window, then click on the [Remove] button. The trace name listed in the [Files to Edit] window will be removed.

- To remove all trace files from the print list displayed in the [Files to Edit] window, click on the [Remove All] button. All trace names listed in the [Files to Edit] window will be removed.
- 7 To activate editable text fields, select corresponding check boxes.
 - 8 Edit text fields as needed.
 - 9 Choose OK to complete changes.

Section 6: Printing Trace Reports

Selecting a Printer

The [Printer Setup] command, allows you to select a printer and set up the printing options.

- 1 From the [File] pull down menu, choose the [Printer Setup] command. The [Print Setup] dialog box will be displayed (see Figure 6-1).
- 2 Click on the [Down arrow] button at the end of the [Name] pull down list to display the available printers.
- 3 From the displayed list, select the desired printer.

Note: If you have a PDF printer installed, you may select it for producing trace reports in the PDF file format.

- 4 If needed, you may click on the [Properties] button to display the [Printing Preferences] dialog box and change settings that affect the way documents are printed.
- 5 When all settings are complete, click on the [OK] button.




Figure 6-1: Print Setup Dialog Box.

Printing a Single Trace Report

There are two ways to print a single trace currently displayed in the [Trace graph] window:

- Click on the Toolbar Print  icon. Clicking this icon allows you to print directly to the default printer.

OR

- From the [File] menu, select the [Print] command. The [Print] dialog box will be displayed (see Figure 6-2).

Activating this command allows you to select a printer and set up printing preferences.

- Select the desired printer by clicking on its icon. Depending on the selected printer, a variety of tabs that represent Printing Preferences will appear on the top of the [Print] dialog box.
- Click each tab to see the available choices. Change options as needed.
- When all settings are complete, click on the [Print] button.




Figure 6-2: Print Dialog Box.

Printing Multiple Trace Reports - Batch Printing

For printing multiple trace reports, Trace600 provides the Batch Print feature, which simplifies printing operations by allowing multiple trace reports to be printed automatically. Using the [Batch Print] command, all trace files that require printing can be selected and processed at once. This is done in the [Batch Print] dialog box.

Batch Print Dialog Box

The table below gives a summary of the [Batch Print] dialog box features (refer to Figure 6-3).

Ref #	Feature	Description
1	[Drive] window	Allows you to navigate to the desired folder
2	[Files in Folder] window	Displays all trace files in the currently selected folder
3	[Files to Print] window	Displays all trace files added to the print list
4	[Trace Preview] window	Allows you to view the selected trace graph
5	[Cover Page] check box	Check this box if you prefer to print a summary page
6	[Cover Page Setup] button	Allows you to access the [Cover Information] dialog box and add necessary information to a summary page
7	[Add] button	Adds a single trace or multiple traces to the print list
8	[Add All] button	Allows you to add all traces to the print list
9	[Remove] button	Removes a single trace or multiple traces from the print list
10	[Remove All] button	Allows you to remove all traces from the print list

11	[Zoom] arrow buttons	Allows you to set up a zoom level for all traces in the print list
12	[Print Files] button	Sends the created batch print job to a printer
13	[Exit] button	Closes the [Batch Print] dialog box




Figure 6-3: Batch Print Dialog Box.

Selecting Traces for Batch Print

- 1 From the [File] menu, select the [Batch Print] command to access the [Batch Print] dialog box (refer to Figure 6-3).
- 2 In the [Drive] window, locate and select the desired folder.
- 3 Double-click on the selected folder to open it.
- 4 All trace files in the open folder will be displayed in the [Files in Folder] window.
- 5 If you need to view a trace graph before adding a trace file to the print list, use the [Trace Preview] window.
 - Click on the desired trace name listed in the [Files in Folder] window to display the selected trace graph in the [Trace Preview] window.
- 6 From the [Files in Folder] window, add the desired traces to the print list, which will be displayed in the [Files to Print] window. Use the [Add] or [Add All] buttons for adding trace files.
 - To add trace files individually:

Double-click the desired trace name listed in the [Files in Folder] window. The trace name added to the print list will appear in the [Files to Print] window.

OR

Click on the desired trace name listed in the [Files in Folder] window, then click on the [Add] button. The trace name added to the print list will appear in the [Files to Print] window.
 - To add all trace files in the current folder to the print list, click on the [Add All] button. The added trace names will appear in the [Files to Print] window.

- 7 You may set horizontal and vertical zoom level for all trace files in the current folder. The zoom level you set for one trace applies to all traces in the current folder.
 - Use the [Zoom] arrow buttons to set horizontal and vertical zoom level.
- 8 If you need to remove trace files from the print list displayed in the [Files to Print] window, use the [Remove] or [Remove All] buttons.
 - To remove trace files from the print list individually:
Double-click the desired trace name displayed in the [Files to Print] window. The trace name listed in the [Files to Print] window will be removed.

OR


Click on the desired trace name displayed in the [Files to Print] window, then click on the [Remove] button. The trace name listed in the [Files to Print] window will be removed.
 - To remove all trace files from the print list displayed in the [Files to Print] window, click on the [Remove All] button. All trace names listed in the [Files to Print] window will be removed.
- 9 To create a Cover page for trace reports, click on the [Cover Page Setup] button (refer to the section titled “Creating a Cover Page” for more information).
- 10 To print a Cover page in addition to trace reports, verify that the [Include Cover Page] check box is selected.
- 11 When all settings are complete, click on the [Print Files] button to send the batch print job to a printer.

Creating a Cover Page for your Batch Print Job

Trace600 allows you to create a cover page for your multiple printing. To create a cover page, perform the following steps.

- 1 From the [File] menu, select the [Batch Print] command to access the [Batch Print] dialog box (refer to Figure 6-3).

Note: When you access the [Batch Print] dialog box, the [Cover Page Setup] function is not available - the [Cover Page Setup] button is grayed out. To make the [Cover Page Setup] button active, you need to create a batch print list. At least one trace file needs to be added to a print list, which is displayed in the [Files to Print] window.




To print a cover page in addition to trace reports, verify that the [Include Cover Page] check box is selected.

- 2 Create a batch print list (refer to the section titled “Selecting Traces for Batch Printing”).
- 3 Click on the [Cover Page Setup] button to access the [Cover Information] dialog box.

The [Cover Information] dialog box is divided into several sections with editable text fields as follows.

Report Title field

This is a text field where you enter a title for your batch print job.



Company Information section

This section contains text fields where you enter company name and address.

Company Information			
Company Name:	<input type="text" value="Noyes"/>		
Address:	<input type="text"/>		
City:	<input type="text"/>		
State/Prov:	<input type="text"/>	Postal Code:	<input type="text"/>
Country:	<input type="text"/>		


Cable Information section

This section contains text fields where you enter all information you need to identify a cable.

Cable Information	
Test Site:	<input type="text"/>
Far Site:	<input type="text"/>
Cable ID:	<input type="text"/>
Cable Type:	<input type="text"/>
Tested By:	<input type="text"/>

Job Description section

This section contains text fields where you enter the information required to identify a job.



The image shows a dialog box with a light gray background and a thin border. On the left side, there are four labels: "Job Description:", "Prepared By:", "Phone:", and "Email:". To the right of each label is a corresponding text input field. The "Job Description" field is a large rectangular box. The "Prepared By:", "Phone:", and "Email:" fields are smaller, single-line text boxes. All fields are currently empty.

- 5 When you finish entering all the necessary information, click on the [OK] button to return to the [Batch Print] dialog box.

Thank you for choosing Noyes Test & Inspection

16 Eastgate Park Road
Belmont, NH 03220
Phone: 800-321-5298
603-528-7780

Fax: 603-528-2025

www.AFLtele.com > Products > Noyes Test & Inspection

