

Figure 1

1. INTRODUCTION

These MEB jam-nut receptacle connectors are designed to be installed onto mil-tactical jacketed fiber optic cable with aramid strength members.

NOTE



Dimensions in this instruction sheet are in millimeters [with inches in brackets]. Figures are not drawn to scale.

The connector must be assembled using a receptacle connector shell kit, an EB insert assembly kit, ferrule assembly kit (one for each fiber or channel), and a cable adapter kit. Sample part numbers are given in Figure 1. The combination of the kits selected is based on the diameter of the cable, the mode and quantity of fibers, and the operating wavelength of the system.

CAUTION



To avoid poor optical performance or permanent damage to the lens of the EB insert, use ONLY Tyco Electronics ferrule assembly kits. Other manufacturers' ferrule assemblies ARE NOT compatible with the EB insert assembly kit.

These connectors are designed to be rear panel mounted.

2. DESCRIPTION

Each kit contains the components shown in Figure 1.

The EB insert assembly kit is shipped with a white protective label on the back (end opposite the lens) of the EB insert which is installed immediately after final testing to keep the channel cavities clean. The EB insert is ready for assembly as shipped.

3. HANDLING

DANGER



To avoid personal injury, NEVER look into the end of terminated or unterminated optical fibers. Laser radiation is invisible but can damage eye tissue.

- Do not touch the lens of the EB insert with your fingers or with any tools

NOTE



If the lens is touched or otherwise contaminated, clean the lens according to Instruction Sheet 408-8828.




Figure 2

- After assembly, re-install the protective cap or mate the connector immediately after the cap has been removed to prevent contamination to the EB insert assembly

4. TOOLS AND MATERIALS

The following tools and materials are necessary for preparation, assembly, inspection, and maintenance of the connector and cable assembly. Follow the operating instructions packaged with the tools and safety guidelines packaged with the materials.

NOTE



Items without a part number or supplier are customer supplied.

4.1. Tools

- cable jacket strip tool
- Aramid Shears 1278637-1
- SDE PEW 12 Hand Tool 91382-1 with Die Set 1673667-1 (408-8795)
- micrometer or vernier, dial, or digital caliper
- Fiber Stripping Tool 504024-1 (125- μ m, red handle) (408-9485)
- Heat Cure Oven Assembly 502134-1 (120 Vac) or -2 (240 Vac) includes universal heat cure block (408-9460)
- Curing Fixture 1516296-1 (408-8857)
- Sapphire Scribe Tool 504064-1 (408-4293)
- polishing machine (recommended) or Polishing Bushing 504862-1 (for hand polishing)
- 200 \times Microscope Kit 1754767-1
- Ferrule Insertion Tool 1693820-1
- 2-mm hex wrench
- keyed adapter tool with handle or bench-mount fixture and torque wrench or torque stand †
- 13-mm open-end wrench
- 16-mm open-end wrench
- 27-mm jam-nut socket

BETA is a trademark of Beta Utensili S.p.A.

Loctite, 480, Prism, and 243 are trademarks of Henkel Corporation.

Dow Corning and Molykote are registered trademarks of Dow Corning Corporation.

† BETA backshell assembly tools from Daniels Manufacturing Corporation is recommended.

For catalog, visit: http://www.dmctools.com/_pdf/Catalogs/BetaBackshell.pdf

4.2. Materials

- Loctite 480 Prism instant adhesive
- lint-free tissues or cloths
- isopropyl alcohol (99%) or acetone
- Epoxy 504035-1 (4-gram bi-pack)
- Epoxy Applicator Kit 501473-3

For hand polishing only:

- 5- μ m Aluminum Oxide Polishing Film 228433-8
- 1mm Rubber Polishing Pad 501858-1 (green)
- Polishing Plate 501197-1 (216 \times 280 mm)
- 0.3- μ m Diamond Polishing Film 228433-5
- Final Polishing Film 502748-2
- lint-free applicator swabs
- Dow Corning Molykote 55 O-ring grease
- Loctite 243 threadlocker

5. ASSEMBLY PROCEDURE

IMPORTANT: Assemble the connector using a laminar flow table in a clean environment meeting the requirements of International Organization for Standardization (ISO) 14644-1 (Class 5), "Cleanrooms and Associated Controlled Environments, Part 1." Make sure that all components are free from contamination.

Proceed as follows:

5.1. Prepare the Cable

1. Slide the components shown in Figure 2 onto the cable allowing 1 m at the end of the cable for stripping the cable. Make sure to orient each component as shown.

2. Using the cable jacket strip tool, strip the jacket to the dimension shown in Figure 3, exposing the strength members and fiber. Retain the stripped piece of jacket for later use.

Using the shears, trim the strength members to the length given in Figure 3.


Cable Strip Length**Note:** Not to Scale

Figure 3

NOTE

These instructions are for single-channel connectors. For multi-channel connectors, perform the same assembly procedure for each channel.

5.2. Terminate the Fiber

1. Apply a continuous bead of the instant adhesive around the cable jacket between 4 and 5 mm from the stripped end of the jacket. See Figure 4, Detail A.

NOTE

Loctite 480 Prism instant adhesive is a cyanoacrylate which hardens extremely quick.

2. Rotate and slide the crimp support (large diameter end first) over the fiber and strength members and onto the jacket until it bottoms (rotating the crimp support between the thumb and index finger will help feed the strength members through the crimp support). See Figure 4, Detail B.

3. Apply a thin band of the instant adhesive around the knurled portion of the crimp support. Make sure that the band is continuous around the entire circumference. See Figure 4, Detail C.

4. Slide the piece of cable jacket (stripped from the jacket in Paragraph 5.1) over the buffered fiber and into the center of the strength members until it bottoms against the crimp support and the strength members are flared away from the fiber. See Figure 4, Details D and E.

5. Slide the crimp sleeve over the fiber and piece of cable jacket so that the strength members fold back evenly around and over the crimp support and until it bottoms on the rear flange of the crimp support; then remove the piece of cable jacket. This step should be performed quickly before the adhesive begins to harden. See Figure 4, Detail E.






Detail A**Detail B****Detail C****Detail D****Detail E**

Figure 4

6. Place the crimp sleeve in the 8.6-mm hex nest of the hand tool, and crimp the crimp sleeve onto the crimp support. Make sure to position the crimp sleeve in the hex nest so that the crimp will locate from the back of the crimp sleeve to within the dimension shown in Figure 5, Detail A.

7. Using the micrometer or caliper, measure the crimp sleeve across the flats of the hex crimp to make sure that it conforms to the crimp height and crimp width shown in Figure 5, Detail B.

If necessary, crimp again, and re-measure the crimp.

8. At the back of the crimp support, apply the instant adhesive around the circumference of the crimp support at the junction of the cable and the crimp support. Then at the front of the crimp sleeve, apply the instant adhesive over the opening of the crimp sleeve to encapsulate the strength members. See Figure 5, Detail C. Remove any excess adhesive.

9. Mark the fiber at the dimension shown in Figure 5, Detail D, and using the fiber stripping tool, strip the buffer to the mark, exposing the bare fiber. Using a lint-free tissue or cloth dampened with the isopropyl alcohol or acetone, clean the bare fiber.



Take care not to break the bare fiber. If any part of the fiber breaks, the crimp support and crimp sleeve must be replaced, and the cable must be re-stripped.


10. Slide the spring onto the fiber buffer. See Figure 5, Detail E.

11. Pre-heat the heat cure oven to 100°C.


12. Prepare the epoxy according to the following:

- a. Remove the separating clip from the epoxy package. Using the epoxy mixer, mix the two components together thoroughly for 20 to 30 seconds.
- b. Install the needle tip on the applicator from the epoxy applicator kit. Make sure it is secure. Remove the plunger.
- c. Cut the epoxy packet open, and squeeze the epoxy into the back of the applicator. Re-assemble the plunger. Hold the applicator vertically, and slowly push on the plunger until the entrapped air escapes and a bead of epoxy appears at the needle tip.
- d. Using a lint-free tissue or cloth dampened with the isopropyl alcohol or acetone, clean the tip of the applicator.


Detail A




Detail B



Detail C



Detail D



Detail E




Figure 5

13. Hold the ferrule assembly vertically, and insert the needle tip into the base of the ferrule assembly until it is against the back (end closest to the base) of the ferrule assembly. Refer to Figure 6.

14. While holding the ferrule assembly *firmly* against the needle tip, *slowly* inject the epoxy until a small bead of epoxy (approximately 0.75 mm in diameter) forms at the end face of the ferrule assembly. DO NOT allow the bead to get too large or smear.

15. Withdraw the needle slightly, and inject an additional small amount of epoxy so that the cavity at the base of the ferrule assembly is approximately one-third to one-half full.

DANGER

To avoid personal injury, remember that epoxy is a hazardous material, and pay particular attention to the following:

- ALWAYS follow manufacturer's safety guidelines.
- ALWAYS wear protective gloves when using epoxy.
- ALWAYS use epoxy in a well ventilated area.
- AVOID prolonged and frequent contact with skin.
- AVOID inhaling fumes from epoxy.

16. Place the crimp sleeve and fiber into the curing fixture according to the instructions included with the curing fixture.

Carefully insert the fiber into the back of the ferrule assembly (previously prepared with epoxy). Simultaneously slide and rotate the ferrule assembly on the fiber (to prevent any air pockets from being trapped in the epoxy) until it bottoms. Make sure that the bare fiber is protruding from the end face of the ferrule assembly. If it is not, re-strip and re-terminate the fiber.

Place the ferrule assembly in the curing fixture according to the instructions included with the curing fixture.

17. Cure the assembly in the heat cure oven for 20 minutes. Remove the assembly from the oven, and allow the assembly to cool to room temperature.

18. Measure the assembly to make sure that it conforms to the dimension given in Figure 7. If it does not, re-strip and re-terminate the fiber.

NOTE

Although the curing fixture is designed to ensure that the required functional length is obtained, it is still important to measure the assembly for this length after curing.




Figure 6




Figure 7

5.3. Cleave the Fiber

Firmly support the ferrule assembly, and draw the beveled edge of the scribe tool across the fiber as shown in Figure 8. After scoring the fiber, pull the fiber straight away from the ferrule assembly.

DANGER

Safely dispose of excess fiber.

CAUTION

To avoid damage to the tip of the scribe tool, DO NOT allow the scribe tool to contact the epoxy.




Figure 8

5.4. Polish the Fiber

It is recommended polishing the fiber using a polishing machine. The polish must produce a super-physical contact (PC) end finish for singlemode connectors and a flat end finish for multimode connectors. *Machine polishing produces the best results.* Polish the fiber according to the machine manufacturer's instructions.

If machine polishing is not possible, hand polish the fiber according to the following:

1. Using a small piece of the 5- μ m polishing film, remove the fiber stub to the level of the epoxy.
2. Install the ferrule assembly onto the polishing bushing.
3. For singlemode connectors, place the green polishing pad on the polishing plate. Place the 5- μ m polishing film on the green polishing pad. For multimode connectors, place the polishing plate on a hard flat surface. Place the 5- μ m polishing film on the polishing plate.
4. Hold the ferrule assembly and rest the tips of your index finger, middle finger, and thumb on the top of the polishing bushing. Starting with very light pressure, polish the tip of the fiber in a figure-8 pattern. Refer to Figure 9. Polish the fiber until the epoxy turns a very light yellow.

NOTE



DO NOT remove all the epoxy. As the epoxy gets lighter, check the tip of the fiber frequently.

5. Clean the end face of the ferrule assembly and polishing bushing with isopropyl alcohol or acetone and a lint-free tissue.
6. Place the 0.3- μ m polishing film on the polishing pad (singlemode) or polishing plate (multimode). Polish in a figure-8 pattern. Stop polishing as soon as all the epoxy is removed.
7. Clean the end face of the ferrule assembly and polishing bushing with isopropyl alcohol or acetone and a lint-free tissue.
8. Place the final polishing film on the polishing pad (singlemode) or polishing plate (multimode). Apply several drops of water to an unused area of the film. Move the ferrule assembly in 20-mm circles on the water for 25 seconds.

NOTE



One sheet of final polishing film will be sufficient for 10 to 20 ferrule assemblies.




Figure 9

9. Remove the ferrule assembly from the polishing bushing. Clean the end face and sides of the ferrule assembly with isopropyl alcohol or acetone and a lint-free tissue.

5.5. Inspect the Ferrule Assembly and Fiber

DANGER



Never inspect or look into the end of a fiber when optical power is applied to the fiber. The infrared light used, although it cannot be seen, can cause injury to the eyes.

1. Using the microscope kit, inspect the ferrule assembly and fiber according to the following criteria (refer to Figure 10):
 - Make sure that any epoxy is removed from the ferrule assembly
 - Dirt may be mistaken for small pits. If dirt is evident on the ferrule assembly or fiber, clean with isopropyl alcohol or acetone and a lint-free tissue, then dry
 - Fine polishing lines are acceptable
 - Small peripheral chips (at the outer rim) on the fiber are acceptable
 - Large chips in the center of the fiber and dark scratches are unacceptable, and the fiber must be re-terminated
2. If necessary, install the dust cover onto ferrule assembly to prevent contamination to the end face.




Figure 10

5.6. Complete the Assembly

1. Remove the protective label from the back of the EB insert.
2. Align the end of the ferrule assembly with the appropriate channel cavity of the EB insert, and insert the ferrule assembly into the channel cavity until the O-ring is against the channel cavity. See Figure 11, Detail A. To avoid damage to the fiber, **DO NOT** push the fiber to install the ferrule assembly.

NOTE




Because of the short length of the buffered fibers, the ferrule assemblies for multi-fiber connectors **MUST** be inserted into the channel cavities simultaneously.

IMPORTANT: The channels for each fiber pair are designated on the EB insert with “A1” and “B1,” and “A2” and “B2”. For proper end-to-end system connection, connect A1 to B1, B1 to A1, A2 to B2, and B2 to A2.

3. Slide the spring over the fiber until it is against the O-ring of the ferrule assembly. Using the ferrule insertion tool, push the spring until the ferrule assembly bottoms in the channel cavity (the spring will protrude slightly from the cavity). See Figure 11, Detail B.


Detail A



Detail B



Detail C



Detail D




Figure 11

NOTE



If necessary, to remove the ferrule assembly from the channel cavity, firmly grasp the end of the ferrule assembly (but not the spring) with the needle-nose pliers, and pull it out of the cavity.

4. Align the index pin hole of the ferrule plate with the index pin at the back of the EB insert, and slip the fiber into the closest slotted hole in the ferrule plate. See Figure 11, Detail C.
5. Hold the ferrule plate against the EB insert, making sure that the index pin enters the index hole. Thread the screw through the screw hole in the ferrule plate and into the hole in the EB insert. See Figure 11, Detail D. Using the 2-mm hex wrench and torque wrench or torque stand, tighten the screw to a torque between 0.8 and 1 N-m. Check to make sure that the ferrule plate is flush with the EB insert.

6. Using an applicator swab, apply a *thin film* of the O-ring grease around the O-ring of the EB insert. Refer to Figure 12, Detail A.



To avoid contaminating optical components, **DO NOT** use heavy deposits of the grease.

7. Mount the housing onto the keyed adapter tool or bench-mount fixture. Align the internal key (small bar inside) of the housing with the keyway (slot along the side) of the EB insert, and slide the EB insert assembly into the housing. See Figure 12, Detail B.

8. Using the 2-mm hex wrench, push the EB insert assembly into the housing until it bottoms (there will be a tactile “click” as the O-ring of the EB insert seats into place in the housing). To avoid damage to the fiber, **DO NOT** push the fiber or cable to install the EB insert assembly.

9. Slide the wave spring and compression sleeve over the crimp sleeve and into the housing. See Figure 12, Detail C.

10. Apply 2 to 3 drops of the threadlocker to the threads at the front of the collet sleeve. See Figure 12, Detail D.

11. Slide the collet sleeve over the crimp sleeve and into the housing. Refer to Figure 12, Detail D. Thread the collet sleeve onto the housing, **BEING VERY CAREFUL NOT** to pinch the end of the collet sleeve which would cause the cable to twist. Using the 13-mm open-end wrench and torque wrench or torque stand, tighten the collet sleeve to a torque between 3 and 4 N-m.


12. Using an applicator swab, apply a *thin film* of the O-ring grease to the housing O-ring, threads at the back of the collet sleeve, and the ramp of the collet sleeve. Refer to Figure 12, Detail E.

13. Slide the collet nut onto the collet sleeve. See Figure 12, Detail E. Using the 13-mm open-end wrench and torque wrench or torque stand, tighten the collet nut to a torque between 1 and 2 N-m.

14. Slide the washer against the collet sleeve. See Figure 12, Detail F.


Detail A

O-Ring of EB Insert
Apply Thin Film of O-Ring Grease Here




Detail B


Internal Key of Housing
(Visible Inside Housing)



Keyway of
EB Insert




Detail C




Detail D

Apply Threadlocker Here
Threads at Front of Collet Sleeve



Detail E

Apply Thin Film of O-Ring Grease Here
Threads at Back of Collet Sleeve
Housing O-Ring
Ramp of Collet Sleeve



Detail F




Figure 12

15. Slide the cable seal over the cable until it is approximately 10 mm from the washer. See Figure 13, Detail A.

16. Apply the O-ring grease to the front and back and to the outside diameter of the cable seal. Also, apply the grease around the cable jacket between the cable seal and the washer. See Figure 13, Detail B.

17. Apply several drops of the threadlocker to the threads of the housings. See Figure 13, Detail B.

18. Apply a *thin film* of the O-ring grease to the inside edge of the extension (this is necessary to prevent damage to the O-ring of the housing). See Figure 13, Detail C.


19. Slide the extension over the collet nut, and thread the extension onto the housing. Using the 16-mm open-end wrench and torque wrench or torque stand, tighten the extension to a torque between 4 and 6 N-m.

20. Remove the housing from the keyed adapter tool or bench-mount fixture.


21. Apply the instant adhesive completely around the cone of the extension. See Figure 13, Detail D.

22. Slide the boot over the cone of the extension until it is tight against the shoulder of the extension. See Figure 13, Detail E. Remove any excess adhesive.


Detail A




Detail B



Detail C



Detail D



Detail E




Figure 13

5.7. Mount the Connector onto the Panel and Install the Protective Cap

1. Cut the panel using the dimensions provided in Figure 14.

NOTE



Make sure that the flat edge is located in position to match the established rotational orientation.

2. Make sure that the flange O-ring is installed in the groove of the housing flange (refer to Figure 1). Then, install the connector through the back of the panel so that the O-ring on the shoulder of the housing is flat against the panel. See Figure 15, Detail A.

3. Slide the tether loop of the protective cover over the threads at the front of the flange of the housing. See Figure 15, Detail A.

4. Thread the panel nut onto the housing. See Figure 15, Detail A. Using the jam-nut socket and torque wrench, tighten the panel nut to a torque between 20 and 30 Nm. The O-ring will be compressed and the tether loop will be captured between the panel nut and panel.

5. Thread the protective cap onto the housing. Hand-tighten the protective cap. See Figure 15, Detail B.

6. REPLACEMENT AND REPAIR

Components are not repairable. DO NOT use any damaged or defective components. DO NOT re-use the crimp support, crimp sleeve, or ferrule assembly by removing the fiber.

Order replacement parts through your Tyco Electronics representative, or call 1-800-526-5142, or send a facsimile of your purchase order to 717-986-7605, or write to:

CUSTOMER SERVICE (038-035)
TYCO ELECTRONICS CORPORATION
PO BOX 3608
HARRISBURG PA 17105-3608

7. REVISION SUMMARY

- Initial release of instruction sheet

Recommended Panel Cutout
Panel Thickness Range 1.58-3.2 mm





Figure 14

Detail A



Detail B




Figure 15