

2017 ROTARY WING CAPABILITIES

	OEM P/N	LORD P/N	PART DESCRIPTION	SERVICE TYPE	LORD Price
BELL 206 SERIES					
	206-011-139-001	J-14258-3	Arm Assy (Flap Restraint)	Overhaul Exchange	\$613
	206-030-539-101	LB9-1301-1-1	Mount Assy (Pylon)	Overhaul Exchange	\$3,458
	206-033-501-001	LB1-1010-4-1	Support Assy (Forward)	Overhaul Exchange	\$15,419
	206-033-501-003	LB1-1010-6-1	Support Assy, LH	Overhaul	Contact LORD
	206-033-501-004	LB1-1010-6-2	Support Assy, RH	Overhaul	Contact LORD
	206-033-501-101	LB1-1010-22-1	Support Assy, LH	Overhaul Exchange	\$9,041
	206-033-501-102	LB1-1010-22-2	Support Assy, RH	Overhaul Exchange	\$9,041
Upgrade Available ▲	206-033-506-101	J-15413-17	Restraint, Transmission	Overhaul Exchange	\$9,530
	206-033-506-101	J-15413-17	Restraint, Transmission	Repair	\$1,003
	206-033-506-107	J-15413-20	Restraint, Transmission	Overhaul Exchange	\$9,530
	206-033-506-107	J-15413-20	Restraint, Transmission	Repair	\$1,003
	206-033-506-109	J-15413-21	Restraint, Transmission	Overhaul Exchange	\$9,530
	206-033-506-109	J-15413-21	Restraint, Transmission	Repair	\$1,650
	206-033-516-101	LB9-1010-1-2	Flexure Assy	Overhaul Exchange	\$10,147
	206-033-518-005	J-15424-2	Stop Assy (Upstop)	Overhaul Exchange	\$315
	206-033-518-007	J-15425-2	Stop Assy (Downstop)	Overhaul Exchange	\$413
	206-033-544-001	LB9-1010-8-1	Support Assy, Isolation	Overhaul	\$4,476
	206-033-554-101	LB6-1010-16-1	Link Assy (Pylon)	Overhaul Exchange	\$3,886
Pending EASA Approval	206-310-004-101	LORD206-310-004101	Tension Torsion (TT) Strap	New/PMA	\$3,059
Pending EASA Approval	206-310-004-103	LORD206-310-004103	Tension Torsion (TT) Strap	New/PMA	\$3,389
EASA Approved	Replaces: one 206-011-812-005, two B-2012, two 53642-75, two 206-411-814-003, two 206-011-862-001	LB2-1010-20-1	Elastomeric TR Trunnion Kit	STC/PMA	\$5,557
EASA Approved	Replaces: one 206-011-812-005, two B-2012, two 53642-75, two 206-411-814-003, two 206-011-862-001	LB2-1010-20-2	Elastomeric TR Trunnion Bearing	STC/PMA	\$4,247
	407-312-100-101	LB2-1232-1-1	Bearing, Flapping - Tail Rotor	Overhaul Exchange	\$4,716
BELL 407					
	407-310-100-105	J-17750-24	Main Rotor Hub Damper	Overhaul Exchange	\$5,173
	407-310-100-107	J-17750-25	Main Rotor Hub Damper (Blue Coat)	Overhaul Exchange	\$5,173
SPEIIA-equipped part	407-310-101-107	LB9-1232-7-1	Shear Bearing	Overhaul Exchange	\$5,265
SPEIIA-equipped part	407-310-101-105	LB9-1232-6-1	Shear Bearing (Blue Coat)	Overhaul Exchange	\$5,265
SPEIIA-equipped part	407-310-102-101	LB4-1232-3-1	Lead Lag Bearing	Overhaul Exchange	\$6,159
SPEIIA-equipped part	407-310-102-103	LB4-1232-7-1	Lead Lag Bearing (Blue Coat)	Overhaul Exchange	\$6,159
	407-310-203-101	LB1-1232-5-1	Corner Mount	Overhaul Exchange	\$2,487
	407-312-100-101	LB2-1232-1-1	Tail Rotor Flapping Bearing	Overhaul Exchange	\$4,716
New Offering	407-010-100 Series	REP-407-010-100 Series	Main Rotor Hub	Overhaul	Contact LORD
BELL 412					
	204-031-920-003	J-9797-6	Damper Assy	Overhaul Exchange	\$1,473
	204-031-920-003 (Repair Kit)	J-16656-1	Repair Kit for Damper Assy	New	\$648
	204-031-927-107	J-8085-50	Mount Assy	Overhaul Exchange	\$2,133
	204-031-920-003	J-9993-3	Boot For Damper Assy	New	\$342
	204-031-920-003	J-9994-1	Housing for Damper Assy	New	\$955
	204-031-920-003	Y-16960-3-1	Inner Member for Damper Assy	New	\$1,002
	212-030-436-007	J-15452-3	Landing Gear Strap	Overhaul Exchange	\$587
SPEIIA-equipped part	412-010-106-101	REP412-010-106-101	Bonded Pivot Bearing	Repair Exchange	\$12,834
Upgrade Available ▲	412-010-145-105	J-16663-4	Damper Yoke Set (Qty 4) ▽▽	Overhaul Exchange	\$10,129
	412-310-146-103	J-16663-7	Damper Yoke Set (Qty 4)	Overhaul Exchange	\$13,021

2017 ROTARY WING CAPABILITIES

repairstation@lord.com

	OEM P/N	LORD P/N	PART DESCRIPTION	SERVICE TYPE	LORD Price
BELL 412					
SPEIIA-equipped part	412-010-190-103	LB9-1062-8-2N	Spindle ▽ ☒	Overhaul	\$25,086
SPEIIA-equipped part	412-010-190-103	REPLB9-1062-8-2N	Spindle ▽ ☒	Repair	\$20,174
SPEIIA-equipped part	412-010-190-105	LB9-1062-18-1N	Spindle ▽ ☒	Overhaul	\$22,221
SPEIIA-equipped part	412-010-190-105	REPLB9-1062-18-1N	Spindle ▽ ☒	Repair	\$18,012
	412-030-437-103	J-16883-2	Aft Landing Gear Cap Assy	Overhaul Exchange	\$1,247
	412-330-437-101	J-16883-9	Aft Landing Gear Cap Assy	Overhaul Exchange	\$1,647
	412-330-437-103	J-23381-5	Rubber Bumper	Overhaul Exchange	\$1,132
Fluid Resistant	412-340-102-101	REP412-340-102-101	Transmission Boot	Overhaul Exchange	\$2,290
New Offering	412-010-100 Series	REP-412-010-100 Series	Main Rotor Hub	Overhaul	Contact LORD
BELL 204, 205, 212					
	204-031-920-003	J-9797-6	Damper Assembly	Overhaul Exchange	\$1,473
	204-031-920-003	J-16656-1	Damper Assembly Repair Kit	New	\$648
	204-031-927-005	J-8085-6	Bonded Tube Form	Overhaul Exchange	\$1,203
	204-031-927-007	J-8085-8	Bonded Tube Form	Overhaul Exchange	\$1,203
	204-031-920-003	J-9993-3	Boot For Damper Assy	New	\$342
	204-031-920-003	J-9994-1	Housing for Damper Assy	New	\$955
	204-031-920-003	Y-16960-3-1	Inner Member for Damper Assy	New	\$1,002
	212-030-273-001	J-14105-1	Fwd Cap Landing Gear Assy	Overhaul Exchange	\$1,360
	212-030-274-001	J-14106-1	Aft Cap Landing Gear Assy	Overhaul Exchange	\$1,126
	212-030-436-007	J-15452-3	Landing Gear Strap	Overhaul Exchange	\$587
	212-030-437-007	J-15452-4	Landing Gear Strap	Overhaul Exchange	\$667
BELL 429					
Upgrade Available ◀	429-310-003-101	LB4-1274-4-1	CF Bearing (Blue Coat)	Overhaul Exchange	\$8,713
	429-310-003-103	LB4-1274-5-1	CF Bearing (Blue Coat)	Overhaul Exchange	\$8,298
	427-310-201-107	FL-1087-4	Vertical Live Mount	Overhaul Exchange	\$47,486
Upgrade Available ◀	429-310-001-105	J-23813-2	Lead-Lag Damper	Overhaul Exchange	\$8,817
	429-310-001-109	J-23813-4	Lead-Lag Damper	Overhaul Exchange	\$8,397
	429-310-201-105	J-23823-12	Pitch Restraint Assembly	Overhaul Exchange	\$8,950
BELL 430					
	430-310-101-107	LB9-1220-2-5	Shear Restraint ☒	Overhaul	\$9,473
Pending EASA approval	430-310-104-105	FL-1030-8	Damper, Blade Set (Qty 2)	Rebuild Exchange	\$23,727
	430-310-200-107	FL-1027-7	Fluid Mount ☒	Overhaul	\$49,281
BELL 214 SERIES					
	214-010-158-001	LB1-1003-1-1	Bearing Assy, Flapping	Overhaul	\$27,267
	214-030-614-003	LB9-1004-15-3	Torsion Arm Assy, Pylon Support, LH	Overhaul	\$30,287
	214-030-614-004	LB9-1004-15-4	Torsion Arm Assy, Pylon Support, RH	Overhaul	\$30,287
	214-030-615-003	LB9-1004-3-3	Clevis Assy, Pylon Support, LH	Overhaul	\$29,024
	214-030-615-004	LB9-1004-3-4	Clevis Assy, Pylon Support, RH	Overhaul	\$29,024
	214-031-612-115	J-17746-5	Spring, Elastomeric, Fwd and Aft	Overhaul	\$9,286
	214-031-614-105	LB9-1004-29-7	Arm Assy, LH	Overhaul	\$58,227
	214-031-614-107	J-16644-5	Plate Assy	Overhaul	\$12,454
	214-031-614-108	J-16644-6	Plate Assy	Overhaul	\$13,695
	214-031-614-125	LB9-1004-29-14	Arm Assy, RH	Overhaul	\$55,483
	214-031-614-127	J-16644-17	Plate Assy	Overhaul	\$12,234
	214-031-614-128	J-16644-18	Plate Assy	Overhaul	\$12,390
	214-031-615-105	LB9-1004-20-9	Clevis Assy, LH	Overhaul	\$40,453
	214-031-615-106	LB9-1004-20-10	Clevis Assy, RH	Overhaul	\$39,946

2017 ROTARY WING CAPABILITIES

repairstation@lord.com

OEM P/N	LORD P/N	PART DESCRIPTION	SERVICE TYPE	LORD Price	
BELL 214 SERIES					
214-031-617-113	LB9-1004-45-1	Spring	Overhaul	\$16,821	
BELL 222 / 230					
222-031-605-109	LB9-1302-5-1	Flex Assy [☒]	Overhaul	\$21,215	
222-310-117-105	LB5-1078-19-1	Spring	Overhaul Exchange	\$5,018	
222-331-617-103	LB1-1302-4-2	Isolation Mount, Lateral	Overhaul Exchange	\$7,911	
222-331-618-105	LB1-1302-3-1	Isolation Mount, Longitudinal	Overhaul Exchange	\$6,574	
BELL 427					
427-310-201-103	FL-1044-3	Live Mount	Overhaul Exchange	\$39,854	
407-310-100-107	J-17750-25	Main Rotor Hub Damper (Blue Coat)	Overhaul Exchange	\$5,173	
407-310-101-107	LB9-1232-6-2	Shear Bearing ^{▽▽}	Overhaul Exchange	\$5,420	
407-310-102-101	LB4-1232-3-1	Lead Lag Bearing ^{▽▽}	Overhaul Exchange	\$6,159	
407-310-102-103	LB4-1232-7-1	Lead Lag Bearing (Blue Coat) ^{▽▽}	Overhaul Exchange	\$6,159	
407-312-100-101	LB2-1232-1-1	Tail Rotor Flapping Bearing	Overhaul Exchange	\$4,716	
MD 500					
369A1724-7	LB2-1056-17-1	Bearing (Tail Rotor Teetering)	New/PMA	\$1,154	
369D21400-503	J-15640-6	Main Rotor Damper	New/PMA	\$2,709	
369D21721-21	369D21721-21	Fork Assy (Tail Rotor)	Overhaul	\$4,604	
SCHWEIZER 300					
New Offering	269A1290-003	J-15640-14	Main Rotor Blade Damper Assembly	New/PMA	\$3,084
New Offering	269A5667-003 Replaces: -005	LB2-1222-2-1	Tail Rotor Elastomeric Teeter Bearing	New/PMA	\$909
HILLER					
	21075	J-10114-19	Torsion Engine Drive Coupling	New	Contact LORD

☒ Life-limited part. Historical Record Card required for overhaul/repair.

▽ LORD can upgrade the LB9-1062-8-2N (412-010-190-103) to the LB9-1062-18-1N (412-010-190-105)

▽▽ LORD can upgrade the J-16663-4 (412-010-145-105) to the J-16663-7(412-310-146-103)

All sales subject to LORD Terms and Conditions. Prices subject to change.

LORD and "Ask Us How" are trademarks of LORD Corporation or one of its subsidiaries.

LORD provides valuable expertise in adhesives and coatings, vibration and motion control, and magnetically responsive technologies. Our people work in collaboration with our customers to help them increase the value of their products. Innovative and responsive in an ever-changing marketplace, we are focused on providing solutions for our customers worldwide ... Ask Us How.

LORD Corporation
World Headquarters
 111 Lord Drive
 Cary, NC 27511-7923
 USA

Parts handled directly by LORD
may be shipped DDP to:
 LORD Corporation
 Attn: Repair Station
 2455 Robison Road West
 Erie, PA 16509 USA
 repairstation@lord.com

Customer Support Center (in United States & Canada)
 +1 877 ASK LORD (275 5673)
 www.lord.com/mro
 Email: customer.support@lord.com; repairstation@lord.com
 For a listing of our worldwide locations, visit LORD.com.

