LORD AEROSPACE MRO SERVICES

2016 ROTARY WING CAPABILITIES

	OEM P/N	LORD P/N	PART DESCRIPTION	SERVICE TYPE	LORD Price	OEM 2015 List Price
			BELL 206 SERIES			
	206-011-139-001	J-14258-3	Arm Assy (Flap Restraint)	Overhaul Exchange	\$607	\$1,012
	206-030-539-101	LB9-1301-1-1	Mount Assy (Pylon)	Overhaul Exchange	\$3,424	\$6,887
	206-033-501-001	LB1-1010-4-1	Support Assy (Forward)	Overhaul Exchange	\$15,266	\$23,331
	206-033-501-003	LB1-1010-6-1	LH Support Assy	Overhaul	Contact LORD	
	206-033-501-004	LB1-1010-6-2	RH Support Assy	Overhaul	Contact LORD	
	206-033-501-101	LB1-1010-22-1	LH Support Assy	Overhaul Exchange	\$8,951	\$14,450
	206-033-501-102	LB1-1010-22-2	RH Support Assy	Overhaul Exchange	\$8,951	\$14,450
	206-033-506-101	J-15413-17	Transmission Restraint	Overhaul Exchange	\$9,436	
	206-033-506-101	J-15413-17	Transmission Restraint	Repair	\$993	
	206-033-506-107	J-15413-20	Transmission Restraint	Overhaul Exchange	\$9,436	\$15,415
	206-033-506-107	J-15413-20	Transmission Restraint	Repair	\$993	\$15,415
	206-033-506-109	J-15413-21	Transmission Restraint	Overhaul Exchange	\$9,436	\$15,415
	206-033-506-109	J-15413-21	Transmission Restraint	Repair	\$1,634	\$15,415
	206-033-516-101	LB9-1010-1-2	Flexure Assy	Overhaul Exchange	\$10,047	\$19,274
	206-033-518-005	J-15424-2	Stop Assy (Upstop)	Overhaul Exchange	\$312	\$510
	206-033-518-007	J-15425-2	Stop Assy (Downstop)	Overhaul Exchange	\$409	\$706
	206-033-544-001	LB9-1010-8-1	Isolation Support Assy	Overhaul	\$4,432	\$7,374
	206-033-554-101	LB6-1010-16-1	Link Assy (Pylon)	Overhaul Exchange	\$3,848	\$6,332
Pending EASA Approval	206-310-004-101	LORD206-310-004101	Bell 206 TT Strap	New	\$3,059	\$4,294
Pending EASA Approval	206-310-004-103	LORD206-310-004103	Bell 206 TT Strap	New	\$3,389	\$4,779
Pending EASA Approval	Replaces: one 206-011- 812-005, two B-2012, two 53642-75, two 206-411- 814-003, two 206-011- 862-001	LB2-1010-20-1	Elastomeric TR Trunnion Kit	STC/PMA	\$5,502	
Pending EASA Approval	Replaces: one 206-011- 812-005, two B-2012, two 53642-75, two 206-411-814-003, two 206-011-862-001	LB2-1010-20-2	Elastomeric TR Trunnion Bearing	STC/PMA	\$4,205	
	407-312-100-101	LB2-1232-1-1	Tail Rotor Flapping Bearing	Overhaul Exchange	\$4,624	\$7,324
			BELL 407			
	407-310-100-105	J-17750-24	Main Rotor Hub Damper	Overhaul Exchange	\$5,072	\$8,858
	407-310-100-107	J-17750-25	Main Rotor Hub Damper (Blue Coat)	Overhaul Exchange	\$5,072	\$8,858
SPEIIA- equipped part	407-310-101-107	LB9-1232-7-1	Shear Bearing	Overhaul Exchange	\$6,790	\$10,509
SPEIIA- equipped part	407-310-101-105	LB9-1232-6-1	Shear Bearing (Blue Coat)	Overhaul Exchange	\$5,162	\$10,181
SPEIIA- equipped part	407-310-102-101	LB4-1232-3-1	Lead Lag Bearing	Overhaul Exchange	\$6,038	\$9,023
SPEIIA- equipped part	407-310-102-103	LB4-1232-7-1	Lead Lag Bearing (Blue Coat)	Overhaul Exchange	\$6,038	\$9,023
- 4	407-310-203-101	LB1-1232-5-1	Corner Mount	Overhaul Exchange	\$2,438	\$4,297
	407-312-100-101	LB2-1232-1-1	Tail Rotor Flapping Bearing	Overhaul Exchange	\$4,624	\$7,324
New Offering	407-010-100 Series	REP-407-010-100 Series	Main Rotor Hub	Overhaul	Contact LORD	\$318,429

2016 ROTARY WING CAPABILITIES

	OEM P/N	LORD P/N	PART DESCRIPTION	SERVICE TYPE	LORD Price	OEM 2015 List Price
			BELL 412			
	204-031-920-003	J-9797-6	Damper Assy	Overhaul Exchange	\$1,458	\$2,346
	204-031-920-003 (Repair Kit)	J-16656-1	Repair Kit for Damper Assy	New	\$611	
	204-031-927-107	J-8085-50	Mount Assy	Overhaul Exchange	\$2,112	\$3,752
	204-031-920-003	J-9993-3	Boot For Damper Assy	New	\$332	
	204-031-920-003	J-9994-1	Housing for Damper Assy	New	\$901	
	204-031-920-003	Y-16960-3-1	Inner Member for Damper Assy	New	\$945	
	212-030-436-007	J-15452-3	Landing Gear Strap	Overhaul Exchange	\$581	\$1,226
SPEIIA- equipped part	412-010-106-101	REP412-010-106-101	Bonded Pivot Bearing	Repair Exchange	\$12,834	\$23,924
Upgrade Available	412-010-145-105	J-16663-4	Damper Yoke Set (Qty 4) ^{▽▽}	Overhaul Exchange	\$10,029	\$14,143
	412-310-146-103	J-16663-7	Damper Yoke Set (Qty 4)	Overhaul Exchange	\$12,892	\$22,260
SPEIIA- equipped part	412-010-190-103	LB9-1062-8-2N	Spindle [▽] ^図	Overhaul	\$24,838	\$51,430
SPEIIA- equipped part	412-010-190-103	REPLB9-1062-8-2N	Spindle [▽] 🗵	Repair	\$19,974	\$51,430
SPEIIA- equipped part	412-010-190-105	LB9-1062-18-1N	Spindle [▽] 🗵	Overhaul	\$22,001	\$49,918
SPEIIA- equipped part	412-010-190-105	REPLB9-1062-18-1N	Spindle [▽] 🗵	Repair	\$17,834	\$49,918
equipped part	412-030-437-103	J-16883-2	Aft Landing Gear Cap Assy	Overhaul Exchange	\$1,235	\$3,420
	412-330-437-101	J-16883-9	Aft Landing Gear Cap Assy	Overhaul Exchange	\$1,631	\$3,420
	412-330-437-103	J-23381-5	Rubber Bumper	Overhaul Exchange	\$1,121	\$2,102
Fluid Resistant	412-340-102-101	REP412-340-102-101	Transmission Boot	Overhaul Exchange	\$2,290	\$3,370
New Offering	412-010-100 Series	REP-412-010-100 Series	Main Rotor Hub	Overhaul	Contact LORD	\$844,979
			BELL 204, 205, 212			
	204-031-920-003	J-9797-6	Damper Assembly	Overhaul Exchange	\$1,458	\$2,346
	204-031-920-003	J-16656-1	Damper Assembly Repair Kit	New	\$611	
	204-031-927-005	J-8085-6	Bonded Tube Form	Overhaul Exchange	\$1,146	\$1,746
	204-031-927-007	J-8085-8	Bonded Tube Form	Overhaul Exchange	\$1,146	\$1,712
	204-031-920-003	J-9993-3	Boot For Damper Assy	New	\$332	
	204-031-920-003	J-9994-1	Housing for Damper Assy	New	\$901	
	204-031-920-003	Y-16960-3-1	Inner Member for Damper Assy	New	\$945	
	212-030-273-001	J-14105-1	Fwd Cap Landing Gear Assy	Overhaul Exchange	\$1,295	\$1,936
	212-030-274-001	J-14106-1	Aft Cap Landing Gear Assy	Overhaul Exchange	\$1,072	\$1,572
	212-030-436-007	J-15452-3	Landing Gear Strap	Overhaul Exchange	\$581	\$1,226
	212-030-437-007	J-15452-4	Landing Gear Strap	Overhaul Exchange	\$635	\$1,244
			BELL 429			
Upgrade Available	429-310-003-101	LB4-1274-4-1	CF Bearing (Blue Coat)	Overhaul Exchange	\$8,298	\$12,718
Available	429-310-003-103	LB4-1274-5-1	CF Bearing (Blue Coat)	Overhaul Exchange	\$8,298	\$12,718
	427-310-201-107	FL-1087-4	Vertical Live Mount	Overhaul Exchange	\$45,225	\$67,332
Upgrade	429-310-001-105	J-23813-2	Lead-Lag Damper	Overhaul Exchange	\$8,397	\$11,152
Available <	429-310-001-109	J-23813-4	Lead-Lag Damper	Overhaul Exchange	\$8,397	\$11,152
	429-310-201-105	J-23823-12	Pitch Restraint Assembly	Overhaul Exchange	\$8,524	\$12,022
					. ,	. ,- =

2016 ROTARY WING CAPABILITIES

	OEM P/N	LORD P/N	PART DESCRIPTION	SERVICE TYPE	LORD Price	OEM 2015 List Price
			BELL 430			
	430-310-101-107	LB9-1220-2-5	Shear Restraint [⊠]	Overhaul	\$9,022	\$15,969
Pending EASA approval	430-310-104-105	FL-1030-8	Damper, Blade Set (Qty 2)	Rebuild Exchange	\$22,597	\$47,211
App 2	430-310-200-107	FL-1027-7	Fluid Mount	Overhaul	\$46,934	\$80,636
			BELL 214 SERIES			
	214-010-158-001	LB1-1003-1-1	Flapping Bearing Assy	Overhaul Exchange	\$25,969	
	214-030-614-003	LB9-1004-15-3	LH Pylon Support Torsion Arm Assy	Overhaul Exchange	\$28,845	
	214-030-614-004	LB9-1004-15-4	RH Pylon Support Torsion Arm Assy	Overhaul Exchange	\$28,845	
	214-030-615-003	LB9-1004-3-3	LH Pylon Support Clevis Assy	Overhaul Exchange	\$27,642	
	214-030-615-004	LB9-1004-3-4	RH Pylon Support Clevis Assy	Overhaul Exchange	\$27,642	
	214-031-612-115	J-17746-5	Fwd and Aft Elastomeric Spring	Overhaul Exchange	\$8,844	\$13,171
	214-031-614-105	LB9-1004-29-7	LH Arm Assy	Overhaul Exchange	\$55,454	
	214-031-614-107	J-16644-5	Plate Assy	Overhaul Exchange	\$11,861	
	214-031-614-108	J-16644-6	Plate Assy	Overhaul Exchange	\$13,043	
	214-031-614-125	LB9-1004-29-14	RH Arm Assy	Overhaul Exchange	\$52,841	
	214-031-614-127	J-16644-17	Plate Assy	Overhaul Exchange	\$11,651	
	214-031-614-128	J-16644-18	Plate Assy	Overhaul Exchange	\$11,800	
	214-031-615-105	LB9-1004-20-9	LH Clevis Assy	Overhaul Exchange	\$38,527	
	214-031-615-106	LB9-1004-20-10	RH Clevis Assy	Overhaul Exchange	\$38,044	\$57,225
	214-031-617-113	LB9-1004-45-1	Spring	Overhaul Exchange	\$16,020	
			BELL 222 / 230			
	222-031-605-109	LB9-1302-5-1	Flex Assy [⊠]	Overhaul	\$20,205	\$39,193
	222-310-117-105	LB5-1078-19-1	Spring	Overhaul Exchange	\$4,779	\$6,919
	222-331-617-103	LB1-1302-4-2	Lateral Isolation Mount	Overhaul Exchange	\$7,534	\$11,128
	222-331-618-105	LB1-1302-3-1	Longitudinal Isolation Mount	Overhaul Exchange	\$6,261	\$9,248
			BELL 427			
	427-310-201-103	FL-1044-3	Live Mount	Overhaul Exchange	\$37,956	\$70,865
	407-310-100-107	J-17750-25	Main Rotor Hub Damper (Blue Coat)	Overhaul Exchange	\$5,072	\$8,858
	407-310-101-107	LB9-1232-6-2	Shear Bearing ^{▽▽}	Overhaul Exchange	\$5,162	
	407-310-102-101	LB4-1232-3-1	Lead Lag Bearing ^{▽▽}	Overhaul Exchange	\$6,038	\$9,023
	407-310-102-103	LB4-1232-7-1	Lead Lag Bearing (Blue Coat) ^{▽▽}	Overhaul Exchange	\$6,038	\$9,023
	407-312-100-101	LB2-1232-1-1	Tail Rotor Flapping Bearing	Overhaul Exchange	\$4,624	\$7,324
			MD 500			
	369A1724-7	LB2-1056-17-1	Bearing (Tail Rotor Teetering)	New	\$1,110	\$3,038
	369D21400-503	J-15640-6	Main Rotor Damper	New	\$2,709	\$5,055
	369D21721-21	369D21721-21	Fork Assy (Tail Rotor)	Overhaul	\$4,514	\$12,427



2016 ROTARY WING CAPABILITIES

	OEM P/N	LORD P/N	PART DESCRIPTION	SERVICE TYPE	LORD Price	OEM 2015 List Price		
	SCHWEIZER 300							
New Offering	269A1290-003	J-15640-14	Main Rotor Blade Damper Assembly	New	\$2,980			
New Offering	269A5667-003 Replaces: -005	LB2-1222-2-1	Tail Rotor Elastomeric Teeter Bearing	New	\$878			
	HILLER							
	21075	J-10114-19	Torsion Engine Drive Coupling	New	Contact LORD			

 $^{^{\}boxtimes}$ Life-limited part. Historical Record Card required for overhaul/repair.

All sales subject to LORD Terms and Conditions. Prices subject to change.

LORD and "Ask Us How" are trademarks of LORD Corporation or one of its subsidiaries.

LORD provides valuable expertise in adhesives and coatings, vibration and motion control, and magnetically responsive technologies. Our people work in collaboration with our customers to help them increase the value of their products. Innovative and responsive in an ever-changing marketplace, we are focused on providing solutions for our customers worldwide ... Ask Us How.

LORD Corporation World Headquarters 111 Lord Drive Cary, NC 27511-7923

USA

Parts handled directly by LORD may be shipped DDP to: LORD Corporation Attn: Repair Station 2455 Robison Road West Erie, PA 16509 USA

Customer Support Center (in United States & Canada)

+1 877 ASK LORD (275 5673)

www.lord.com/mro

Email: customer.support@lord.com

For a listing of our worldwide locations, visit LORD.com.

LORDAskUsHow™

[∇] LORD can upgrade the LB9-1062-8-2N (412-010-190-103) to the LB9-1062-18-1N (412-010-190-105).

 $^{^{\}triangledown\triangledown}$ LORD can upgrade the J-16663-4 (412-010-145-105) to the J-16663-7(412-310-146-103)