

HALCoGen 04.04.00

Release Notes

3rd Apr 2015

HALCoGen™ is the driver generation tool for TI's Hercules Microcontroller Family

Copyright © 2003-2015 Texas Instruments Incorporated. All rights reserved.

Information in this document is subject to change without notice. Texas Instruments may have pending patent applications, trademarks, copyrights, or other intellectual property rights covering matter in this document. The furnishing of this documents is given for usage with Texas Instruments products only and does not give you any license to the intellectual property that might be contained within this document. Texas Instruments makes no implied or expressed warranties in this document and is not responsible for the products based from this document.

TABLE OF CONTENTS

1	New In This Release.....	3
2	System Requirements	3
3	Installing HALCoGen	4
4	Uninstall HALCoGen	4
5	Release Contents.....	5
6	Fixed In This Release	7
7	Known Issues and Limitations	8
8	User Notes	9

1 New In This Release

- Bug Fixes and few GUI Enhancements.
- Added I2C – PCF8570 Example
- Added HALCoGen + Safety Library Example for all families
- Added MIBSPI Tick Trigger Example.
- Bundled Safety Diagnostic Library V2.2.0
- Bundled F035 Flash API V1.09
- Bundled F021 Flash API V2.01.01

Note:

For all HALCoGen FreeRTOS based projects used with CCS, in the Compiler options under Advanced Options → Language Options → "Enable support for GCC Extension (--gcc)".

Note:

For TMS570LC43x and RM57x Family of Devices Safety Functions are support only in SafeTI Diagnostic Library version 2.1.0 which can be installed along with HALCoGen 4.01.00 or later.

For using SafeTI Diagnostic Library with HALCoGen please refer Examples → example_SafetyLib.c in following Help file
C:\ti\Hercules\HALCoGen\v04.04.00\help\TMS570LC43x.chm (or)
C:\ti\Hercules\HALCoGen\v04.04.00\help\RM57Lx.chm

2 System Requirements

The system requirements for HALCoGen are as follows:

OS – Windows XP, Windows 7

Memory – 1GB

Disk Space – 750 MB

3 Installing HALCoGen

The Latest HALCoGen version can also be downloaded from the following Link <http://www.ti.com/tool/halcoген>.

The tool gets installed in the directory named **.\HALCoGen\vXX.YY.ZZ**

Where **XX.YY** is the version number and **ZZ** is the Patch number if released. Multiple versions can co-exist, although it is advised to use the latest version.

4 Uninstall HALCoGen

The HALCoGen can be uninstalled one version at a time.

ti → Hercules → HALCoGen → vXX.YY.ZZ → uninstall.exe

5 Release Contents

This release supports the drivers for the following variants:

Modules	<i>TMS470M</i>	<i>TMS570LS 20x</i>	<i>TMS570LS 31x/RM48x</i>	<i>TMS570LS 12x/RM46x</i>	<i>TMS570LS 09x/07x/R M44x</i>	<i>TMS570LS 04x/RM42x</i>	<i>TMS570LC 4x/RM57x</i>
Cortex-R4	-	✓	✓	✓	✓	✓	-
Cortex-R5	-	-	-	-	-	-	✓
Cortex-M3	✓	-	-	-	-	-	-
freeRTOS	✓	✓	✓	✓	✓	✓	-
SYSTEM	✓	✓	✓	✓	✓	✓	✓
PINMUX	-	-	✓	✓	✓	✓	✓
MPU	✓	✓	✓	✓	✓	✓	✓
PMU	-	✓	✓	✓	✓	✓	✓
VIM	✓	✓	✓	✓	✓	✓	✓
ESM	-	✓	✓	✓	✓	✓	✓
Memory Map	✓	✓	✓	✓	✓	✓	✓
RAM	✓	✓	✓	✓	✓	✓	✓
FLASH	✓	✓	✓	✓	✓	✓	✓
GCM/Oscillator	✓	✓	✓	✓	✓	✓	✓
PLL	✓	✓	✓	✓	✓	✓	✓
DCC	-	-	✓	✓	✓	✓	✓
CCM	-	x	x	x	x	x	x
PMM	-	-	✓	✓	✓	✓	✓
POM	-	x	✓	✓	-	-	✓
EMIF	-	x	✓	✓	-	-	✓
PBIST	-	✓	✓	✓	✓	✓	x
LBIST(STC)	✓	x	✓	✓	✓	✓	x
MBIST	✓	x	✓	✓	✓	✓	x
EFUSE	-	-	✓	✓	✓	✓	x
RTP-IO	-	-	✓	-	-	-	x
DMM-IO	-	-	✓	-	-	-	x
ETPWM	-	-	-	✓	✓	-	✓
ECAP	-	-	-	✓	✓	-	✓
EQEP	-	-	-	✓	✓	✓	✓

- ✓ Available
- x Not Available
- Not Applicable

Modules	TMS470 M	TMS570L S20x	TMS570L S31x/ RM48x	TMS570L S12x/ RM46x	TMS570L S09x/07x/ RM44x	TMS570L S04x/ RM42x	TMS570LC 4x/RM57x
RTI	✓	✓	✓	✓	✓	✓	✓
GIO	✓	✓	✓	✓	✓	✓	✓
SCI	✓	✓	✓	✓	✓	✓	✓
LIN	✓	✓	✓	✓	✓	✓	✓
SPI	✓	✗	✓	✓	✓	✓	✓
SPI/MIBSPI	✓	✓	✓	✓	✓	✓	✓
CAN	✓	✓	✓	✓	✓	✓	✓
ADC	✓	✓	✓	✓	✓	✓	✓
HET	✓	✓	✓	✓	✓	✓	✓
HTU	-	✗	✗	✗	✗	✗	✗
I2C	-	-	✓	✓	✓	✗	✓
EMAC	-	-	✓	✓	-	-	✓
DMA	-	✗	✓	✓	✓	✓	✓
PCR	-	✗	✓	✓	✓	✓	✓
EPC	-	-	-	-	-	-	✓
NMPU	-	-	-	-	-	-	✓
USB	-	-	- / ✓	- / ✓	-	-	-
FlexRay™	-	-	✗ / -	✗ / -	-	-	✗
FTU	-	-	✗ / -	✗ / -	-	-	✗
FEE	✓	-	✓	✓	✓	✓	✓

- ✓ Available
- ✗ Not Available
- Not Applicable

6 Fixed In This Release

Following are the list of issues fixed in version 04.04.00 from 4.03.00

References	Description
SDOCM00114949	Startup: unmatched #endif when generating for TMS570LC4357 causes compile error.
SDOCM00115003	DCC: Incorrect handling of GCTRL register in dccEnableNotification and dccDisableNotification APIs
SDOCM00115005	DCC: dccSelectClockSource isn't writing the required Key when selecting Clock Source for Counter1
SDOCM00115084	SAFETYINIT: PBIST check on ROM is always enabled, need user config.
SDOCM00115255	ETPWM: Wrong clock displayed in ETPWM HALCoGen GUI.
SDOCM00115256	SAFETYINIT: Bug in errata_PBIST_4 function, the cycle count check math considers wrong ROMDIV.
SDOCM00115259	LINKER CMD: Error in linker command file generated for device TMS570LS1224PGE_FREERTOS causing build error.
SDOCM00115351	SCI: Applicable only to TMS470M devices, Global Structure used in sci.c must have separate TX and RX Buffers.
SDOCM00115352	GIO: Missing GIO Register Definition EMU1 and EMU2 in reg_gio.h.

7 Known Issues and Limitations

Following are the list of Known issues and limitations in this version.

References	Description
SDOCM00084753	<p>SYS: Since the PLL tab does not spit out warnings if any final or intermediate frequencies generated are out of spec.</p> <p>Root Cause: HALCoGen Engine limitation.</p> <p>Workaround: Refer the device Technical Reference Manual for recommended PLL configurations.</p>
SDOCM00086009	<p>Tool: No KEIL tool support for TMS470M devices</p>
SDOCM00087899	<p>FEE: The FEE driver GUI in TMS470Mx family only supports 10 blocks.</p> <p>Root Cause: GUI support is complex since it's not dynamic.</p> <p>Workaround: Generated Header file can be edited manually to required blocks.</p>
SDOCM00095488	<p>CAN: Support for Mixed mode in CAN driver is necessary.</p> <p>Root Cause: GUI support is complex.</p> <p>Workaround: Using User Code section Mailbox configuration can be changed.</p>
SDOCM00088096	<p>ADC: Interrupt Enable Check box for Event, Group1 and Group2 groups for ADC1, ADC2 in HCG.</p> <p>Root Cause: GUI support is complex.</p> <p>Workaround: Separate API's are supported in the driver. Interrupt can be enabled by calling the Enable Notification API.</p>

8 User Notes

- 02.xx.xx HALCoGen Pjt cannot not be opened in 03.xx.xx or greater HALCoGen versions. User has to redo configuration with latest HALCoGen.
- Any directory should not have more than one HALCoGen project (.hcg and .dil files). Each project should be in an individual directory.
- From HALCoGen Version 3.00.00 onwards the header files are generated in include directory and other driver files in source directory. The user needs to set this include path in the 'project include settings' while building it.
(Eg: In compiler (cl470) add option → "--include path (**path**)/include").
- When selecting HET2 – Advanced Configuration Mode / Disable Black box user must make sure the "Select Header File & Source file" inputs are generated out of NHET assembler using option "-n1 -hc32".
- HALCoGen does not delete any files placed/generated under source or include folder generated by HALCoGen.
- To use USB drivers in RM48x and RM46x family of devices Enable support for GCC extensions (--gcc) in compiler options.
- If running CPU Self test in debug mode, the debug info are lost immediately after CPU self test eg., All breakpoints set before CPU self test are lost.
- CCM Self test cannot be run in debug mode.
- HALCoGen must be used with default 100% Font size only.
<http://e2e.ti.com/support/microcontrollers/hercules/f/312/t/184660.aspx>
- Following options must be selected under **MULTI IDE** project to use HALCoGen generated code for GHS.
 - **-T** < Generated code path > \source\sys_link.cmd
 - **-I** < Generated code path > \include
 - **-no_auto_interrupt_table**
 - **-e resetEntry**