M310 Software Release Notes

Changes made in v2.3.15

- New Feature added to access Event table directly from LinkMap screen.
- Minor bug fixes
- Language updates

Changes made in v2.3.05

- LinkMap added for all M310 model
- Macrobend detection and Bi-directional Averaging Analysis (Advanced Analysis) is standard now on all M310 models
- DFS inspection scope supporting software is now standard on all M310 models for plug and play.
- Option added for including or excluding last event in pass/fail
- Option added to turn ON or OFF on Front Panel and First Connector Check
- Warning icon is no longer displayed. Error message log can still be downloaded from System Setting menu.
- Increase limits on jobs, cables, locations, operators, etc. from 99 to 200

Changes made in v2.2.81

- Address defect of unit not responding after update to v2.2.74 from v2.2.53
- Increase limits on locations, operators, cables, .etc from 99 to 200 items.

Changes made in v2.2.74

- TruEvent™ updated to latest version
- OLS feature added (For unit software version v2.2.53 and lower, OLS feature can only be enabled after update unit software version to v2.2.74 and higher AND purchase OLS feature activation key from manufacture)

Changes made in v2.2.53

- Enhanced Event Analysis Software , TruEvent™ added
- Chinese language support added