List of V9 functions with limitations

No	Function	Item	6.0.19.0 at present	Remarks
1	Overlap	Superimpose: area transparent	Y	
2		Superimpose: transparent color	N	Unable to support
3		Superimpose: display on top	N	Unable to support
4	Input	Input type: Direct	Y	GD-80 conversion
5	Alarm logging	Real time printing	*	* ESC/P-R, PictBridge: Unable to support
6	Memory card mode	Parts supported	Y	
7		Memory card device	Y	
8		Card data conversion tool	Y	
9	Remote desktop		N	Available in December, 2016.
10	Printer	PR-201, ESC-P, ESC/P-R, PictBridge HP, CBM, MR-400	Y	
11		EPSON STYLUS PHOTO, STYLUS C86/C65	N	Unable to support
12	PLC ladder transfer	A series CPU	*	* Some part of the functions are limited.
13		Siemens PPI	Y	
14		Siemens MPI	Y	
15	Storage setting	Store the patterns into the storage	Y	
16		Store the messages into the storage in BIN format	Y	
17		Store the messages into the storage in TXT format	Y	
18		Store the screen program into the storage	Y	
19		Store the 3D parts into the storage	Y	
20		Store the Windows fonts into the storage	Y	
21	TELLUS and V-Server	Compatibility with V9	N	Available in December, 2016.
22	SRAM over quota	Logging server	Y	
23		Alarm server	*	* Necessary to reduce the number of sampling count.
24	Video input (1CH)	Optional unit (GUR-04) required	Y	
25	RGB input (1CH)	Optional unit (GUR-01) required	Y	
26	RGB output (1CH)	Optional unit (GUR-02) required	Y	
27	Video input (4CH)	Optional unit (GUR-00) required	Y	
28	Video/RGB input (video 2CH/RGB 1CH)	Optional unit (GUR-10) required	Y	
29	RGB input (2CH)	Optional unit (GUR-11) required	Y	