



**Notice of Designation of
Discontinued MOS ICs
(Affected products: Products listed below)**

Thank you for using SANYO semiconductor products. We will be introducing the technology mentioned in the title as described below. Please take note of this introduction.

Memorandum

Affected Products:

Replacement products or similar products **provided**

Category	Type number	Replacement product	Category	Type number	Replacement product
Digital clock	LM8560B	LM8560N	Electronic volume and tone control	LC75384 Series	LC75410
Electronic tuning	LC7217	LC7218		LC75385 Series	LC75411
	LC7217M			LC75386 Series	LC75412

Replacement product or similar product **not provided**

Category	Type number	Category	Type number	Category	Type number
Digital clock	LM8560NC-Z1	Function switch	LC7825E	CD-DSP	LC7861N
Communications	LM7006		LC7826E		LC7861NE
	LM7007M		LC7830		LC7861NE-R
	LM7008HM	LC7265	LC7861RE		
	LM7008NM	LC7267	LC78622KE		
FM multiplex	LC72707E	Electronic tuning with LCD driver	LC7584CHIP		LC7863KA
Electronic tuning	LC72131D-U	Graphic equalizer	LC7584-XXX		LC7866E
	LC72131D-Z		LC7523M		LC7867EMT
	LC72132M		LC7523		LC7867RE
	LC72136	LC7522	LC78686E		
	LC72136M	LC7534M	LC7868E		
	LC7218HS-ST	LC7537NST	LC7868KE		
	LC7218ST	LC7538M	LC7890A		
	LM7001JUST	LC75394E	LC78602E		
	LM7005	LC75396E	LC78602NE		
LM7005F	LC7860KA	LC7860D			
Function switch	LC7818	CD-DSP	LC7861E	-	-

Date of Implementation:

April 2001.

Contact your SANYO sales representative if you have any questions or require more detailed information regarding this change.