

V-MUX Vista IV OS Release Notes

Version 1.13

Released: 09/15/2016

Feature Additions

1. None

Feature Modifications

1. None

Code Corrections

1. USB Download to Hercules-04
 - a. Corrected an issue where a USB download from the Vista IV to a Hercules-04 node could occasionally cause the Hercules-04 to not load properly and no longer operate.
2. Button Repeat
 - a. Corrected an issue with Button Repeat property where a button with this property set to True would operate incorrectly when pressing the button multiple times rather than just holding it down.

As with all of our software updates, Weldon tries to ensure that no software bugs are introduced. We do however recommend testing the software using your designs to ensure that we have not changed functionality that your designs require in any way.