

MANIFOLDS DRAWING INDEX

DRAWING NAME	DRAWING NO.	MODEL BREAKDOWN	
		Process Connection	Instrument Connection
Gauge Valve Style A	A 07618-Valve-04-V02-1VA-50	1/2 NPT (male)	1/2 NPT (female)
Gauge Valve Style A	A 07618-Valve-50-V02-1VA-50	1/2 NPT (female)	1/2 NPT (female)
Gauge Valve Style B	A 07618-Valve-50-V02-1VB-50	1/2 NPT (female)	1/2 NPT (female)
2-Valve Style A	A 07618-Valve-04-V02-D-50-PN420	1/2 NPT (male)	1/2 NPT (female)
2-Valve Style B	A 07618-Valve-50-V02-2VB-50	1/2 NPT (female)	1/2 NPT (female)
2-Valve Style C	A07618-Valve-50-V02-2VC-50	1/2 NPT (female)	1/2 NPT (female)
3-Valve Style A	A 07618-Valve-50-V02-3A-DN5-PN420	1/2 NPT (female)	IEC Type A
3-Valve Style B	A 07618-Valve-50-V02-3X-50	1/2 NPT (female)	1/2 NPT (female)
5-Valve Style A	B07618-Valve-50-V02-5A-DNS-PN420	1/2 NPT (female)	IEC Type A
5-Valve Style B	A 07618-Valve-50-V02-5B-50-PN420	1/2 NPT (female)	1/2 NPT (female)