

## Tech Note 071014\_02

Date: July 10, 2014

Product: TK-2.0

Subject: USB Cable and Driver Installation

**Note:** Recommended USB Installation Procedure

- 1. Turn the Controller Board Power Switch "Off".
- 2. Insert the Standard-A USB connector into a USB 2.0 port on your computer.
- 3. Insert the Micro-B USB connecter into the controller.
- 4. Turn the Controller Board Power Switch "On".



Recommended USB Cable Driver Installation

Computer Requirements Operating System: Windows 7 (32/64-bit) USB: Standard-A USB 2.0 port

- 1. Click the Start button, then right click on Computer and click Manage.
- 2. Under "System Tools" click **Device Manager.** (The cable will populate under "Other Devices")
- 3. Right click on BRT Zone Controller and click Update Driver Software.



4. Click Browse my computer for driver software.

	<b>X</b>
😡 🗕 Update Driver Software - BRT Zone Controller	
How do you want to search for driver software?	
Search automatically for updated driver software Windows will search your computer and the Internet for the latest driver software for your device, unless you've disabled this feature in your device installation settings.	
Browse my computer for driver software Locate and install driver software manually.	
	Cancel

5. Browse for USB driver location and click Next.



6. The Blue Ridge Technologies driver package has not been digitally signed yet, click **Install this driver software anyway.** 



 In the Update Driver Software pop-up window, Windows has successfully updated your driver software.

