

Tech Note 121213_01

Date: December 12, 2013

Subject: Transformer Replacement

Product: Retrofit Interior (RI) and Retrofit Kit (RK) Replacement Transformer (TR40-RE)

Note: Recommended Replacement Procedure

Caution: RI and RK require isolated transformers. Use of center tap or similar transformer will damage components.

1. Remove existing transformer.
2. Mount new transformer (RIB Transformer Part Number TR40VA004).
3. Terminate transformer secondary leads to controller (polarity of secondary leads is not specific). Connect transformer primary leads (common and power).

