




① INSTALL TRUNK...




② RIP...



③ SLIDE...



④ SLIP



009-101 Issue 1

CAUTION: Corning Cable Systems recommends the use of safety glasses (spectacles) conforming to ANSI Z87, for eye protection from accidental injury when handling cables or working with fiber.

WARNING: Never look into the end of a fiber or connector that may be carrying laser light. Laser light can be invisible and can damage your eyes. Viewing it directly does not cause pain. The iris of the eye will not close voluntarily as when viewing a bright light. Consequently, serious damage to the retina of the eye is possible. Should accidental exposure to laser light be suspected, arrange for an eye examination immediately.

CAUTION: This pulling grip contains a connectorized cable end. Remove the grip only as directed. **DO NOT CUT OFF THE PULLING GRIP.**

Note: This pulling grip is rated for 100 lb (45.5 kg).

CAUTION: For optimum performance, always keep dust caps on non-mated connectors. Use an MTP cleaning tool (p/n 2104466-01) to clean the connectors before reinstalling them in an adapter.

