

2017 PRICE LIST: F-SERIES REPLACEMENT MOTORS

4-INCH FRAME

Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price
F-4030-Q-H00AA	193488	999-001-0390	\$2,261.00	4 Weeks	\$1,357
FSM430	401-34318-01	999-001-0390	\$2,261.00	4 Weeks	\$1,357
F-4030-Q-H00AN	193489	999-001-0392	\$2,261.00	4 Weeks	\$1,357
FSM430 56C	401-34393-00	999-001-0392	\$2,261.00	4 Weeks	\$1,357
F-4030-Q-H04AA	193490	999-001-0391	\$2,776.00	Stock	\$1,666
FSM430 B24	401-34318-20	999-001-0391	\$2,776.00	Stock	\$1,666
F-4030-Q-H04AN	193491	999-001-0393	\$2,776.00	Stock	\$1,666
FSM430 56C B24	401-34318-26	999-001-0393	\$2,776.00	Stock	\$1,666
F-4030-Q-K00AA	195853	999-001-0409	\$2,416.00	4-6 Weeks	\$1,450
F-4030-Q-K00AN	195858	999-001-0413	\$2,416.00	4-6 Weeks	\$1,450
F-4030-Q-K04AA	195857	999-001-0412	\$2,931.00	4-6 Weeks	\$1,759
F-4030-Q-K04AN	195859	999-001-0414	\$2,931.00	4-6 Weeks	\$1,759
F-4050-Q-H00AA	193493	999-001-0394	\$2,673.00	4 Weeks	\$1,604
FSM460	401-34320-01	999-001-0394	\$2,673.00	4 Weeks	\$1,604
F-4050-Q-H00AN	193494	999-001-0395	\$2,673.00	Stock	\$1,604
FSM460 56C	401-34320-06	999-001-0395	\$2,673.00	Stock	\$1,604
F-4050-Q-H01AN	195880	999-001-0426	\$3,889.00	4-6 Weeks	\$2,333
F-4050-Q-H04AA	193495	999-001-0396	\$3,600.00	4 Weeks	\$2,160
FSM460 B24	401-34320-20	999-001-0396	\$3,600.00	4 Weeks	\$2,160
F-4050-Q-H04AN	193496	999-001-0397	\$3,600.00	Stock	\$2,160
F-4050-Q-K00AA	195860	999-001-0415	\$2,725.00	4-6 Weeks	\$1,635
FSM460 E5000	401-34320-50	999-001-0415	\$2,725.00	4-6 Weeks	\$1,635
F-4050-Q-K00AN	195862	999-001-0417	\$2,725.00	4-6 Weeks	\$1,635
F-4050-Q-K04AA	195861	999-001-0416	\$3,652.00	4-6 Weeks	\$2,191
F-4050-Q-K04AN	195863	999-001-0418	\$3,652.00	4-6 Weeks	\$2,191
F-4075-R-H00AA	193497	999-001-0398	\$3,034.00	Stock	\$1,820
FSM490	401-34322-01	999-001-0398	\$3,034.00	Stock	\$1,820
F-4075-R-H00AN	193498	999-001-0399	\$3,034.00	4 Weeks	\$1,820
F-4075-R-H01AA	401-34323-01	999-001-0427	\$4,352.00	4-6 Weeks	\$2,611
F-4075-R-H04AA	193499	999-001-0400	\$3,961.00	Stock	\$2,377
FSM490 B24	401-34322-20	999-001-0400	\$3,961.00	Stock	\$2,377
F-4075-R-H01AN		999-001-0389	\$4,352.00	4-6 Weeks	\$2,267
F-4075-R-H04AN	193500	999-001-0401	\$3,961.00	Stock	\$2,377
F-4075-R-K00AA	195852	999-001-0408	\$3,188.00	4 Weeks	\$1,913
F-4075-R-K00AN	193856	999-001-0411	\$3,188.00	4-6 Weeks	\$1,913
F-4075-R-K04AA	195864	999-001-0419	\$4,064.00	4-6 Weeks	\$2,438
F-4075-R-K04AN	195865	999-001-0420	\$4,064.00	4-6 Weeks	\$2,438

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment

2017 PRICE LIST: F-SERIES REPLACEMENT MOTORS

6-INCH FRAME

Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price
F-6100-R-H00AA	193501	999-001-0402	\$3,396.00	4 Weeks	\$2,038
FSM610	401-34324-01	999-001-0402	\$3,396.00	4 Weeks	\$2,038
F-6100-R-H04AA	193502	999-001-0403	\$4,495.00	Stock	\$2,697
F-6100-R-K00AA	193855	999-001-0410	\$3,604.00	4 Weeks	\$2,162
F-6100-R-K04AA	195866	999-001-0421	\$4,595.00	4 Weeks	\$2,757
F-6200-R-H00AA	193503	999-001-0404	\$4,457.00	Stock	\$2,674
FSM620	401-34326-01	999-001-0404	\$4,457.00	Stock	\$2,674
F-6200-R-H04AA	193504	999-001-0405	\$5,393.00	4 Weeks	\$3,236
F-6200-R-K00AA	195867	999-001-0422	\$4,665.00	4 Weeks	\$2,799
F-6200-R-K04AA	195868	999-001-0423	\$5,528.00	4 Weeks	\$3,317
F-6300-R-H00AA	193505	999-001-0406	\$5,819.00	4 Weeks	\$3,491
FSM630	401-34328-01	999-001-0406	\$5,819.00	4 Weeks	\$3,491
F-6300-R-H04AA	193506	999-001-0407	\$6,755.00	3 Weeks	\$4,053
F-6300-R-K00AA	195869	999-001-0424	\$6,027.00	4 Weeks	\$3,616
F-6300-R-K04AA	195870	999-001-0425	\$6,859.00	4 Weeks	\$4,115

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment