



P Material B-H Loop

SYMBOL	CONDITION	VALUE	UNIT
B _s	25 °C, 10kHz, 25 Oe	2750	Gauss
B _r	25 °C, 10kHz	1250	Gauss
H _c	25 °C, 10kHz	5.5	Oersted




P Material B-H Loop

SYMBOL	CONDITION	VALUE	UNIT
B _s	25 °C, 10kHz, 1989 A/m	275	mT
B _r	25 °C, 10kHz	125	mT
H _c	25 °C, 10kHz	438	A/m



Temperature Response of P Material

1MHz



Frequency Response of P Material

