

Installation Instructions

GEN SPEED[®] 10 MTP[™]

Terminates
Easy as 1-2-3!

featuring  **mosaic**
CROSSBLOCK[®]

 **General Cable**

Step 1

Use cable-stripping tool (Panduit #CJAST) to cut back approximately 2" of the cable jacket. The mosaic tape typically removes with the jacket.




Step 2

Peel and remove the overall wrap. Separate the pairs from the Flex-Separator™ and cut the exposed cross-web using snipping tool (Panduit #CWST).




Step 3


Per diagrams below, insert twisted pairs into termination cap to achieve proper orientation of twisted pairs at each cable end. Trim ends and terminate the Panduit Jack (part number CJ6X88TG) using the EGJT termination tool.




Termination Cap



Pair Orientation for Cable End 1



Adjust Pair Position for Cable End 2



Pair Orientation for Cable End 2



4 Tesseneer Drive
Highland Heights, Kentucky
41076-9753

Telephone: (800) 424-5666
(859) 572-8000

www.generalcable.com

590 Barmac Drive
North York, Ontario
M9L 2X8

Telephone: (800) 561-0649
Fax: (800) 565-2529

GENERAL CABLE, FLEX-SEPARATOR, GENSPEED, MOSAIC
CROSSBLOCK and 10 MTP are trademarks of
General Cable Technologies Corporation.

©2009. General Cable Technologies Corporation.
Highland Heights, KY 41076

All rights reserved. Printed in USA.
Form No. DAT-0131-0609