



801 E Mission Rd, San Marcos CA 92069 P: 760-744-0125 F: 760-744-6081 www.sullinscorp.com

FORM  
DOC QF-7.3.7 Rev -  
10/27/2010

**ENGINEERING CHANGE BULLETIN #10016**

**CUSTOMERS' NOTIFICATION OF PART NUMBER CHANGE**

**Date Change Effective: 11/01/2013**

**Explanation of change from existing to new part number:  
Nylon 46 is now obsolete.**

**CUSTOMERS' NOTIFICATION OF PART NUMBER CONFIGURATION REVISIONS**

**Date Change Effective: 11/01/2013**

**Explanation of configuration change/ (From) (To):**

'N'(Nylon 46) material code removed, replaced by 'G'(Nylon 9T)

Changed from:	Changed to:	
N_E__DHRQ-T94_	G_E__DHRQ-T94_	(DWG# 11042)
N_E__DHRN-T94_0	G_E__DHRN-T94_0	(DWG# 11043)
N_E__DHRN-T94_	G_E__DHRN-T94_	(DWG# 11044)

**Existing parts will remain active for purchase? Yes \_\_\_ No X**

'N' material code changed from Nylon 46 to Nylon 9T

N_E140DHHN-T9__	(DWG# 11040)
N_E115DHHN-T9__	(DWG# 11041)
N_E__DHHN-T9__	(DWG# 11045)


**Existing parts will remain active for purchase? Yes X No \_\_\_**

**Configuration impacts for fit, form, and function are:**

Upgrade in material. Improves processing

**New or revised parts are interchangeable to the previous part applications?**

Yes X No \_\_\_

**Engineering Approval:**  **Date:** 11/1/13  
(Signature)

**Distribution:**

**Sales/Purchasing/Manufacturing Operations, Quality Assurance/Document Control, Technical Support, Molding, Kitting**