



## Test Procedure for the NCP456RFCCT2GEVB Evaluation Board

1. Connect strap between IN and Vbias
2. Connect 3.2 V between IN and GND
3. Check  $V_{out} = 0$
4. Set  $EN = 2V$
5. Check  $V_{out} = V_{in}$
6. Set  $EN = 0V$
7. Check  $V_{out}$  decreases down to GND
8. Disconnect  $V_{in}$