

PCN 1408-01

September, 2014

## Product Change Notification

Dear Sir or Madam,

Please be informed about changes in the following products:

Part Description	Part Number MNR	Function
PT2G-SM5.3	1537	PICOTURN Speed sensors for turbochargers
PT2G-SM5.5	1591	
PT2G-SM5.6	1660	
PT2G-SM5F.2	1590	
PT2G-SM5F.3	1538	
PT2G-SM5F.5	1666	
PICOTURN-SM5.1	586	
PICOTURN-SM5.3	933	
PICOTURN-SM5.5	998	
PICOTURN-SM5.6	1059	
PICOTURN-SM5F.2	934	
PICOTURN-SM5F.3	1081	
PICOTURN-SM5F.5	1574	

Description of the changes:

Changes	The internal structure of the sensor is modified in order to achieve a higher sensitivity of the sensor. Coil and ferrite are modified.
Effects	The sensitivity of the sensors is significantly improved. So the problems with critical turbo chargers will be rare. With this higher sensitivity the sensors will more likely be able to work with the titanium wheels.

- 1 / 2 -

PCN 1408-01

- 2 / 2 -

Ph. +49-7244-7419-0  
Fx. +49-7244-7419-29

Email: sales@acam.de  
www.acam.de

Compatibility	<p>The outer dimensions of the sensors stay unchanged.</p> <p>The sensors are 1-to-1 compatible with existing systems and can be connected to existing boxes.</p> <p>The part numbers will be maintained.</p>
Problems	None expected
Schedule	<p>The production will be changed fluently from September 2014. The sensors with new heads will be seen from the date code in the serial number.</p> <p>The old part numbers will be maintained.</p>

acam-messelectronic gmbh

Autor: Norbert Breyer  
Position: Marketing/Sales

Tel: +49 7244 7419 - 21  
Fax: +49 7244 7419 - 29