

QTA Lead time Table

Quick Turn Around is ACB's core business.

14% of the orders are delivered within 3wd

30% within 5wd

59% within 10wd

LT in Working Days >	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Double sided	q				sq										
ML 1 pressing		q			sq										
ML 2 pressings (e.g. 1+x+1)			q			sq									
ML 3 pressings (e.g. 2+x+2)					q				sq						
ML 4 pressings (e.g. 3+x+3)							q								sq
1 => 50 dm2	Leadtimes according to lot size & build (technology)														
51 => 100 dm2															
101 => 250 dm2															
251 => 500 dm2															
>500 dm2: to be discussed	q: best possible lead time sq: standard QTA lead time														

Lead times are subject to capacity availability at time of the order