

Transmission base	IC brand and P/N	Bothhand P/N Apply to Notebook	Bothhand P/N Apply to networking		
			Single Port	Dual Port	Quad Port
	<b>Mstar(MTK group)</b>				
10/100	MSD57xx(STB)		TS21C HF		
10/100	MSD8xxKCVF(DTV)		TS21C HF		
10/100	MSD489(DTV)		TS21C HF		
1000	MSD7Cx9(STB)		GST5009 LF		
	<b>EcoNet (HK,MTK group)</b>				
1000	MT7525			G2PM109N LF	
1000	MT7511(4X10/100+1 Giga)		G1PM109RN LF GST5009B LF	20PT1024RXLF 20PT1024X LF	
1000	MT7525G(4port Giga)			G2PM109RN LF	
1000	MT7530(switch)		GST5009B LF	G2PM109RN LF	
10/100	MT7502		12PS6121C LF		
10/100	MT7510				40SS1041AX HF
10/100	RT63368			20PT1024RXLF 20PT1024X LF	
	<b>MTK</b>				
10/100	LCD-TV MT536X		TS21C HF GST5009 LF		
1000	LCD-TV MT5395		24HSS1041A-2		
	<b>Realtek</b>				
1000	RTL8393(48 port)				GP5429 LF GP5829 LF
1000	RTL8382(24 port)				GP5429 LF GP5829 LF
1000	RTL8380(8 port)				GP5429 LF GP5829 LF
1000	RTL8153(USB to LAN)	GST5009 LF GST5009B LF			
10/100	RTL8152B(USB to LAN)	TS8121A HF			
10/100	RTL8152BN(USB to LAN)	TST1284 LF			
1000	RTL8366S		GST5009 LF	GS5014 LF G2PM109N LF	
1000	RTL8368S		GST5009 LF	GS5014 LF G2PM109N LF	G4P109 LF GP5409 LF
1000	RTL8307	KLA1S109 LF	KLA1S109 LF		
10/100	RTL8309		TS21C HF	LG2P109N LF	40SS1041RX HF
10/100	RTL8316				40SS1041RX HF
10/100	RTL8324				40SS1041RX HF
10/100	RTL8201		12PS6121UX LF TS21C HF		
10/100	RTL8306SD		12PS6121UX LF TS21C HF	20PT1024X LF	
10/100	RTL8139X	NS0013 LF	12PS6121UX LF TS21C HF		
10/100	RTL8201N	NS0013 LF	12PS6121UX LF TS21C HF		
10/100	RTL8102E	NS0013 LF	12PS6121UX LF TS21C HF		
1000	RTL8218F		GST5009 LF	GS5014 LF G2PM109N LF	G4P109 LF GP5409 LF G4P109N-A LF
1000	RTL8111F	GST5009 LF	GST5009 LF		
1000	RTL8329M		GST5009 LF	GS5014 LF G2PM109N LF	G4P109 LF GP5409 LF

1000	RTL8389M		GST5009 LF	GS5014 LF G2PM109N LF	G4P109 LF GP5409 LF
1000	RTL8370(5/8G)		LG1PM109N LF GST5009 LF G1PM109N LF	GS5014 LF G2PM109N LF LG2PM109N LG	G4P109N-A LF
1000	RTL8214		GST5009 LF	GS5014 LF	
10/100	RTL8196C		16PT8520X LF	20PT1024X LF	
10/100	RTL8201CL	NS0013 LF	12PS6121UX LF TS21C HF		
1000	RTL8221B	GST5009 LF	GST5009 LF		
1000	RTL8211	GST5009 LF	GST5009 LF		
10/100	RTL2880		12PS6121UX LF TS21C HF	20PT1024X LF	40SS1041AX HF
10/100	RTL8102E-GR	NS0013 LF	12PS6121UX LF TS21C HF		
10/100	RTL8139D	NS0013 LF	12PS6121UX LF TS21C HF		
10/100	RTL8201CP	NS0013 LF	12PS6121UX LF TS21C HF		
10/100	RTL8671	NS0013 LF	12PS6121UX LF TS21C HF		
10/100	RTL83065D		12PS6121UX LF TS21C HF	20PT1024X LF	
1000	RTL8370(8G)				G4P109N-A LF
1000	RTL8376(16G)				G4P109N-A LF
	<b>Broadcom</b>				
1000	BCM53312				GH5409 LF GH5609S LF
1000	BCM53346				GH5409 LF GH5609S LF
1000	BCM53125			24HSS1041D-2 HF	40SS1041RX-B HF
1000	BCM57780	GST5009B LF			
1000	BCM560500		KLA1S109 LF		
10/100	BCM5906	NS0013 LF			
1000	BCM53115		GST5009 LF	GS5014 LF	
1000	BCM53118		GST5009 LF	GS5014 LF	
1000	BCM5081	GST5009 LF			
10/100	BCM5325		12PS6121UX LF TS21C HF	20PT1024X LF	40SS1041AX HF
1000	BCM54684		GST5009 LF	GS5014 LF	G4P209 LF G4P109 LF GP5409 LF
1000	BCM53314		GST5009 LF	GS5014 LF	G4P109 LF GP5409 LF G4P209NS LF G4P209N LF
1000	BCM96368		GST5009 LF	GS5014 LF	G4P109 LF GP5409 LF
1000	BCM5787		GST5009 LF		
1000	BCM56504		GST5009 LF		
1000	BCM5764		GST5009 LF		
1000	BCM5481		VP6014 HF		
10/100	BCM63XX		12PS6121UX LF TS21C HF	20PT1024X LF	
1000	BCM5464R				GP5409S LF
1000	BCM5488s				GP5409 LF
1000	BCM5248			VP4015 HF VP6015 HF VP7015 HF	
10/100	BCM5356		12PS6121UX LF TS21C HF	20PT1024X LF	40SS1041AX HF
10/100	BCM53101		12PS6121UX LF TS21C HF	20PT1024X LF	40SS1041AX HF

IC Plus				
10/100	IP1826X		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF GS5014 LF 40SS1041AX HF
10/100	IP1717		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
10/100	IP178C		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
10/100	IP178D		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
10/100	IP175C		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
10/100	IP175D		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
1000	IP1001		GST5009 LF	
1000	IP1103		GST5009 LF	
10/100	IP101A		12PS6121UX LF TS21C HF 16PT8520X LF	
10/100	IP210		12PS6121UX LF TS21C HF 16PT8520X LF	
10/100	IP113A/M/S		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
10/100	IP3210		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
1000	IP1725			VP4015 HF VP6015 HF VP6017 HF
<b>MTK(Ralink/Trendchip)</b>				
10/100	TC3162L2X		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
10/100	TC3162HX		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
10/100	TC3162LE		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF
10/100	TC3162P2H		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024X LF 40SS1041AX HF
<b>Intel</b>				
10/100	IXPBP 2400M		12PS6121UX LF TS21C HF	20PT1024SX LF 40SS1041AX HF
1000	ITL82579	GST5009 LF GST5009B LF		
<b>Vitesse</b>				
1000	VSC8504(+MAC)			GH5409 LF GH5609S LF G4P109 LF GP5409 LF
1000	VSC7395X		GST5009 LF	GS5014 LF
1000	VSC8601		GST5009 LF	
1000	VSC8641		GST5009 LF	
1000	VSC7501		GST5009 LF	GS5014 LF G4P109 LF
1000	VSC8538		GST5009 LF	GS5014 LF G4P109 LF

1000	VSC8664		GST5009 LF	GS5014 LF	G4P109 LF
1000	VSC7398 (switch) + Silicon Lab Si3452 (PoE parts)		VP6014 LF		
<b>Marvell</b>					
1000	98DX208+88E1680 RD-DX-8GUNM-B			G2PM109N LF	
1000	98DX216+88E1680 RD-DX-16GUNM-B			GS5014 LF	
1000	98DX224+88E1680 RD-DX-24GUNM-B				G4P209NS LF G4P209RNY LF
1000	MV78230+ 88E1510 RD-AXPWifiAP		24HSS1041A-2 HF		
<b>ASIX Electronics Corporation</b>					
1000	AX88179(USB 3.0)	KLA1S109-43 LF KLA1S109 LF GST5009 LF	KLA1S109-43 LF KLA1S109 LF GST5009 LF		
10/100	AX88796B	KLU1S041 LF TS21C HF TS8121A HF NS0014 LF	KLU1S041 LF TS21C HF TS8121A HF NS0014 LF		
10/100	AX88783	KLU1S041 LF TS21C HF TS8121A HF NS0014 LF	KLU1S041 LF TS21C HF TS8121A HF NS0014 LF		
10/100	AX88742	KLU1S041 LF TS21C HF TS8121A HF NS0014 LF	KLU1S041 LF TS21C HF TS8121A HF NS0014 LF		
10/100	AX88772A (USB to LAN)	KLU1S041 LF TS21C HF TS8121A HF NS0014 LF	KLU1S041 LF TS21C HF TS8121A HF NS0014 LF		
<b>Ralink(MTK group)</b>					
1000	MT7620A + 7530		GST5009B LF	G2PM109RN LF	
1000	MT7621		G1PM109N LF GST5009 LF	G2PM109N LF GS5014 LF	
1000	RT3883			GS5014 LF	
10/100	MT7620+RT5592		NS0013B LF		
10/100	RT3052		12PS6121UX LF TS21C HF 16PT8520X LF	20PT1024SX LF	40SS1041AX HF
1000	RT2880		GST5009 LF	GS5014 LF	
1000	RT2883+RT2853		GST5009 LF	GS5014 LF	G4P109 LF GP5409 LF
10/100	RT63365			20PT1024X LF	
<b>Qualcomm(Atheros)</b>					
1000	QCA7450+AR8035(PLC)		24SH10416 HF 24SH10410 HF		
1000	QCA9558		G1PM109N LF	G2PM109N LF	
1000	QCA8713+8059 (24-Port Giga Switch, with 8 Ports PSE)			VP6015 LF	GP5409-R LF

					GP5409 LF GP5609S LF GP5429 LF GP5829 LF GH5409 LF GH5609S LF
1000	QCA8059				
1000	AR8151	GST5009 LF			
10/100	AR8152(OTT STB)	NS0013 LF NS0014 LF NS0015 LF			
1000	AR8327		G1PM109N LF LG1P109N LF	G2PM109N LF LG2P109N LF	
10/100	AR8032		TS8121CX HF		
1000	QCA8513				GP5409 LF GP5609S LF
	<b>SMSC(Microsemi group)</b>				
10/100	LAN9500		KLU1S041X-43 LF NS0015 LF		
10/100	LAN8720		KLU1S041X-43 LF TS21C HF NS0013B LF NS0013 LF		
	<b>Jmicron</b>				
10/100	JMC260/JMC261	NS0013 LF			
1000	JMC250/JMC251	GST5009 LF 24HSS1041A-2 HF			
	<b>Wiznet</b>				
10/100	W5100		TS8121A HF,		
10/100	W5200		TS8121CX HF,		
10/100	W5300		LU1T516		
10/100	W7100A		KLU1T516-43LF		
10/100	W7200		KLU1S041X-43 LF		
	<b>Digi International</b>				
10/100	Rabbit 6000		TS8121 HF, LU1T516-43 LF		