

BRC64 Release Note

Software Version: v1.2.4.156 Release Date: 2015/03/18

What's New?

- 1. Support Swedish and Croatia language
- 2. Support new camera connectivity method- P2P connection
- 3. Support SQL2012 and pop up message to remind Windows XP users to use SQL2008
- 4. Add streaming buffer for live video smoothness.

Fixed Issues

- 1. Fix crash issue when the image codec is MJPEG
- 2. Fix recording stops issue
- 3. Fix VS-04A no image issue
- 4. Fix video playback error when in Traditional Chinese language
- 5. Enhance auto connecting stability
- 6. Modify for daylight saving time issue

Note

1. BRC64 only supports ONVIF v1.02.

2. For Windows 8 OS, please install the Microsoft SQL 2008 before installing BRC64 software.

Software Version: v1.2.4.151 Release Date: 2014/09/17

What's New?

- 5. Support hydra camera PH-100Ah.
- 6. Support OSD-200Ap dual stream application.
- 7. Modify and update the language string for German.
- 8. Add user authority rule for Remote Playback function.
- 9. Add the option to change the OSD display location.
- 10. Support to set the recording schedule profile to multiple cameras.
- 11. Generic RTSP supports audio function.
- 12. Recycle recording mechanism enhancement.
- 13. Reliability enhancement.

Fixed Issues

- 7. Fix audio and video synchronization.
- 8. Fix the memory leakage issue for edge recording.

Note

- 3. BRC64 only supports ONVIF v1.02.
- 4. For Windows 8 OS, please install the Microsoft SQL 2008 before installing BRC64 software.



Software Version: v1.2.4.124_SP1

Release Date: 2014/03/31

What's New?

1. Support image rotation option on live view and playback.

Fixed Issues

N/A.

Note

1. Using the GenericRTSP connection, the connection status display in main page will always show connected.

2. BRC64 only supports ONVIF v1.02.

Software Version: v1.2.4.124 Release Date: 2014/01/14

What's New?

- 1. Support the de-warp feature for 360 camera (MD-300Np-360, MD-500Ap-360 series)
- 2. Update the Immervision SDK.
- 3. Save panorama PTZ positions, also support pre-set and patrol.
- 4. Update the ActiveX component for the Remote Live and Remote Playback.
- 5. Add Keep Alive mechanism in NVS function.
- 6. Update some strings in France and simple Chinese language.
- 7. Support image rotation function for Live View and Playback.
- 8. Change the default value of recycle recording buffer size.
- 9. Modify the some timer initial sequence.
- 10. System fine tune to reduce the CPU usage.
- 11. Update the behavior for OSD-200A 20xAp searching and connection.
- 12. Modify the Generic RTSP authentication behavior.
- 13. Modify the ONVIF protocol for camera communication.
- 14. Fine tune the watch dog mechanism.
- 15. Enhance the system stability.
- 16. Video Alarm window display in EMap page.
- 17. Store the recording video file in camera name.
- 18. Separate the video recording file stored by hour.
- 19. Re-define the system log information, remove the minor log information.
- 20. Add the text file to record the system information and recording status.
- 21. Add the .Net 2.0 in software installation package.

Fixed Issues

1. Fix memory leakage issue.



- 2. Under EasyLink/DDNS connection type mode, fix the camera connection broken issue when the IP Address changed.
- 3. Fix the potential issue for the recording process.
- 4. Fix the false alarm trigger issue.
- 5. Fix the system monitor fail in PC which has multiple network cards.

Note

- 1. Using the GenericRTSP connection, the connection status display in main page will always show connected.
- 2. BRC64 only supports ONVIF v1.02.

Software Version: v1.2.4.99 Release Date: 2013/05/31

What's New?

1. The software installation package includes the standard and professional version.

- 2. The functions NVS, Video Wall, and Audio Broadcast are supported in professional version only.
- 3. Change the name of PCNVR as BRC64.
- 4. Add the import & export configuration file in setting function.
- 5. Update the file RemoteLV.cab for the remote live view feature.
- 6. Support the Remote Playback function.
- 7. Adding the camera to NVR will not execute the live view decode process by default.
- 8. Add the PC system information display, including the CPU usage, memory usage, and also operation time.
- 9. The CPU usage information will display RED color as warning when over 60%.
- 10. Change to use SQL2005 instead of SQL2008.
- 11. Update the "Max server memory" of SQL to 512MB.
- 12. Support dual stream for the auto switch function.

Fixed Issues

- 1. Fix the video image display abnormal under 5MP resolution.
- 2. Fix can't recording and get snapshot issue when IVA triggered.
- 3. Fix the video delay issue in NVS client when camera connects with GenericRTSP.

Note

1. BRC64 professional version provides 4 channels with full function support.

Software Version: v1.0.4.48 Release Date: 2012/03/15

What's New?

1. Support 4channel video server VS-04A.



- 2. Update the ActiveX component for the remote view.
- 3. Add the convert image file authority in Account Manage function.
- 4. Add the record feature in alarm type.
- 5. Add a selection to disable the live view image when using the Playback function.
- 6. The default player for bic file is set as Video Player.

Fixed Issues

1. Fix the video image display abnormal under 5MP resolution.

Note

N/A

Software Version: v1.0.4.23 Release Date: 2011/11/29

What's New?

- 1. Modify and update the circular recording behavior.
- 2. Using the default username and password to add Brickcom IP Camera by default.
- 3. Right –click the icon in system tray to get the PC-NVR software version information.
- 4. Naming rule update, Snapshot_Matrix_YYYYMMDD-HHMM-SSSS for Snapshot Matrix and Snapshot_SiteXX_CamXX_ YYYYMMDD-HHMM-SSSS for Snapshot Single.
- 5. EMap function supports the minimum monitor resolution 1024x768.
- 6. Modify the reconnect behavior.
- 7. Add the pre-alarm buffer.
- 8. Modify the Zoom in/out behavior, the Zoom in/out function will be e-PTZ when the camera is not the PTZ model.
- 9. Support the System Alarm setting and Camera Event setting.
- 10. Support Sound, Live-view Blinking, Email and FTP notification alarm.
- 11. Add the new PTZ cgi command for Video Server's PTZ function.
- 12. Support Brickcom 5MP IP Camera.
- 13. New Mainconsole GUI design.
- 14. Add auto update feature.
- 15. Support the camera configuration feature, image setting, audio/video setting and pre-view window.
- 16. New VideoPlayer GUI design.
- 17. Support multi-channel playback up to 16channels.
- 18. Add the Forward and Backward function in VideoPlayer.
- 19. Change the converted video file format as AVI.
- 20. Add the Record only mode to hide the Mainconsole GUI.
- 21. Add the Auto Start NVS service feature.
- 22. Support 30 days trail period for Video Wall, NVS, and Audio Broadcast feature.
- 23. Add Proxy feature.

Fixed Issues

1. Fix the redundant pull-down menu on event list page.

Brickcom

- 2. Fix the language issue, there is some English character displayed when using the non-English language.
- 3. Fix the PTZ function.
- 4. Fix the audio issue on playback function.

Note

- 1. PCNVR software will not work when the monitor resolution is below 1024x720.
- 2. Camera Event setting supports Motion Detection, Digital Input event.
- 3. Using the Cmdline to install the SQL Express 2008 R2.
- 4. The multi-language supports German, Dutch, English, Japanese, Russian, Spanish, Portuguese, Thai, Simplified Chinese and Traditional Chinese.
- 5. The license for Video Wall, NVS, and Audio Broadcast feature please contact with support@brickcom.com.

Software Version: v1.0.3.107 Release Date: 2011/08/08

What's New?

- 1. Add the UAC (User Account Control) feature.
- 2. Add the item of retention day function.
- 3. Update the Video Wall feature, support 1x1, 2x2, 3x3 and 4x4.
- 4. Add auto reboot the OS periodically.
- 5. Support the Daylight Saving Time feature.
- 6. Multiple language support Thai.
- 7. Add the hotkey feature
 - F2 to enable all Record
 - F3 to enable all MD Record
 - F4 to disable all Record
 - F5 to set selected camera DI Status to Low
 - F6 to set selected camera Di Status to High
 - F7 to set all cameras DI Status to Low
 - F8 to set all cameras DI Status to High
 - F9 to show DI status in Video Frame (10sec)
- 8. Update some files for the NVS feature.
- 9. Modify the connection behavior when using the EasyLink and DDNS domain name function.
- 10. Enhance the Playback performance and function.
- 11. Add the function to display or hide the Motion Rectangle.
- 12. Support Brickcom 3MP IP Camera.

Fixed Issues

- 1. Fix the audio broadcast issue when adding many sites to broadcast group.
- 2. Update the string on product key dialog window.
- 3. Fix the time displayed error on preview window when enabling daylight saving function.
- 4. Fix the video file convert issue.



N/A

Software Version: v1.0.3.91 Release Date: 2011/04/15

What's New?

- 1. Support Video Wall feature.
- 2. Support NVS feature and add the NVS setting dialog.
- 3. New FFmpeg decoder for Brickcom IP Camera and Playback.
- 4. Modify the circular recording behavior.
- 5. Update the GUI of the Video Player.
- 6. Fine tune the broadcast feature.
- 7. Support Cube LED control.

Fixed Issues

N/A

Note

1. The NVS feature needs the product key to enable.

2. The license for Video Wall, NVS, and Audio Broadcast feature please contact with support@brickcom.com.

Software Version: v1.0.3.87 Release Date: 2011/03/21

What's New?

- 1. Change to use SQL express as the data base structure.
- 2. Multiple language support Russian.
- 3. Support Joystick function.
- 4. Modify the layout of the Playback GUI and add the preview window.
- 5. Modify the progress bar style.
- 6. Support the continuous zoom and focus function.
- 7. Add the flash icon on search camera button.
- 8. The playback video can be searched by date or filename.
- 9. Enable the edge recording function by default.

Fixed Issues

- 1. Playing the offline record file via playback, there is no sound can be heard.
- 2. Configured camera with MJPEG over RTP with quantization table header, the image cannot display properly.
- 3. When user deletes 1st IP Camera in camera list, all of the cameras' motion recording will be disabled automatically.
- 4. The search function in playback cannot work properly, there is no file display in search table.
- 5. Fix the typesetting issue when using the German language. WWW.BRICKCOM.COM | EXPERT IN IP SURVEIL LANCE



Note

N/A

Software Version: v1.0.3.54 Release Date: 2010/10/19

What's New?

- 1. BRC64 supports multiple languages, German, English, Japanese, Russian, Spain, Simple Chinese, and Traditional Chinese
- 2. Modify the behavior to configure IP Camera.
- 3. Add the IE icon for the hyperlink to access IP Camera's web GUI.
- 4. Modify the string for the Schedule Record.
- 5. Fine tune the Motion event alarm and Motion record.
- 6. Remove the resort camera at the Live View menu.
- 7. User can select the Language in Setting Dialog
- 8. Support IE hyper link button for IP Camera's Web GUI.
- 9. Support MJPEG over HTTP, HTTP Tunnel, and Multicast.
- 10. Support Zoom and Focus function for OB-100A series, PZ-040 series and OSD-040 series.
- 11. Support to manual adds the IP Camera with Domain Name and EasyLink domain name.
- 12. Support camera instant reconnection when the connection is broken.
- 13. Remove the MD region mark-up.
- 14. Enhance uninstall feature, user can select to delete or keep the record files, snapshot files, WMV files, setting files and log files.
- 15. Add the offline recording recovery and playback feature.
- 16. The OSD "UPnP Name" will be un-check while user selects "Auto" in Site name.
- 17. User can move the Mainconsole and Playback page.

Fixed Issues

- 1. Modify the Video Player cannot search the video clip.
- 2. Fix the auto-reconnect issue when the network is disconnected.
- 3. Modify the log text string.
- 4. The MD Region notification which configure via IP Camera, it is not sync appear at the PC-NVR Live View.
- 5. When IP Camera multicast and MJPEG over HTTP enabled, it cannot view the streaming and without any warning message.
- 6. Modify some unsuitable translations in the PC-NVR for the Chinese language version.
- 7. Install PC-NVR Spanish language version, the disconnect message on schedule recording page still display English.
- 8. When the internet connection was disconnected, the brightness -/+ buttons will not gray out.
- 9. When user clicks lock button, the buttons of brightness -/+ will not be grayed out.
- 10. The hint message of the volume status is incorrect.

Note

N/A



Software Version: v1.0.3.27 Release Date: 2010/06/14

What's New?

1. Initial Release.

Fixed Issues

N/A

Note

1. BRC64 supports language English, Spanish, and Traditional Chinese.