

<http://www.elwood.com/H-Series.html>

**2017 PRICE LIST: H-SERIES REPLACEMENT MOTORS**

2-INCH FRAME					
Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price
H-2005 (HSM205)	401-34431-00		n/a	Refurbish/Rebuild	\$855
H-2005-K-F00AA	195871		n/a	Refurbish/Rebuild	\$855
H-2005-K-H00AA	193457		n/a	Refurbish/Rebuild	\$855
3-INCH FRAME					
Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price
1326AS-B310H-21	163569	999-001-0011	\$1,699	Stock	\$1,019
1326AS-B310H-21-K3		999-001-0111	\$2,478	4 Weeks	\$1,487
1326AS-B330H-21	163570	999-001-0012	\$1,771	Stock	\$1,063
1326AS-B330H-21-A	195733	999-001-0027	\$2,843	4 Weeks	\$1,706
1326AS-B330H-21-K3		999-001-0065	\$2,541	Stock	\$1,524
H-3007 (163569)	6131-01-802	999-001-0048	\$1,670	Stock	\$1,002
H-3007 (HSM307)	401-34432-00	999-001-0048	\$1,670	Stock	\$1,002
H-3007-N-H00AA	193458	999-001-0048	\$1,670	Stock	\$1,002
H-3007-N-H00AA-AA		999-001-0077	\$1,727	4 Weeks	\$1,036
H-3007-N-H01AA		999-001-0049	\$2,273	4 Weeks	\$1,364
H-3007-N-H01AA-AA		999-001-0155	\$2,331	4 Weeks	\$1,007
H-3007-N-H04AA	193459	999-001-0003	\$2,273	Stock	\$1,364
H-3007-H-K00AA		999-001-0138	\$1,706	4 Weeks	\$778
H-3007/24V BRK	163623	999-001-0003	\$2,273	Stock	\$1,364
H-3016		999-000-9982	\$1,691	3 Weeks	\$1,014
H-3016 (HSM320)	401-34433-00	999-000-9982	\$1,691	3 Weeks	\$1,014
H-3016-N-H00AA	193460	999-000-9982	\$1,691	3 Weeks	\$1,014
H-3016-N-H00AA-AA		999-001-0154	\$1,748	4 Weeks	\$1,049
H-3016-N-H00AX	6133-01-008	999-001-0099	\$1,838	4 Weeks	\$1,103
H-3016-N-H01AA	195850	999-001-0054	\$2,336	4 Weeks	\$1,402
H-3016-N-H01AA-AA		999-001-0156	\$2,383	Stock	\$1,078
H-3016-N-H04AA	193461	999-000-9997	\$2,336	Stock	\$1,402
H-3016-N-K00AA	195814	999-001-0916	\$1,775	4-6 Weeks	\$1,065
H-3016-N-K04AA	6133-01-510	999-000-9986	\$2,415	4 Weeks	\$1,449
H-3016/24V BRK	163624	999-000-9997	\$2,336	Stock	\$1,402
H-3016/24V BRK (HSM320B24)	401-34433-20	999-000-9997	\$2,336	Stock	\$1,402
H-3016/90V BRK (HSM320B90)	401-34433-90	999-001-0054	\$2,336	4 Weeks	\$1,402
H-3016/Flying Leads	191893	Call for P/N	\$1,943	4-6 Weeks	\$1,166

\*Availability is updated weekly and subject to change. Call to confirm.

\*\*Consult factory for model numbers not listed.

\*\*\*All motors built with original design, documentation, and equipment

<http://www.elwood.com/H-Series.html>

**2017 PRICE LIST: H-SERIES REPLACEMENT MOTORS**

4-INCH FRAME					
Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price
1326AS-B420G-21	195734	999-001-0005	\$2,830	Stock	\$1,698
1326AS-B420G-21-AA		999-001-0060	\$3,550	4 Weeks	\$2,130
1326AS-B420G-21-A		999-001-0028	\$3,775	4 Weeks	\$2,265
1326AS-B420G-21-K4		999-001-0084	\$3,363	4 Weeks	\$2,018
1326AS-B440G-21	163572	999-000-9990	\$2,935	Stock	\$1,761
1326AS-B440G-21-A	195735	999-001-0029	\$3,938	4 Weeks	\$2,363
1326AS-B440G-21-K4		999-001-0148	\$3,427	Stock	\$2,056
1326AS-B460F-21		999-001-0007	\$3,040	4 Weeks	\$1,824
1326AS-B460F-21-K4	163627	999-000-9987	\$3,492	Stock	\$2,095
H-4030	163571	Call for P/N	\$1,780	4 Weeks	\$1,068
H-4030 (HSM430)	401-34434-00	999-000-9980	\$1,780	Stock	\$1,068
H-4030-M-H00AA	193462	999-001-0070	\$1,780	4 Weeks	\$1,068
H-4030-M-H00AN	193463	Call for P/N	\$1,780	4 Weeks	\$1,068
H-4030-M-H00AX	6142-01-002	999-001-0107	\$1,782	4 Weeks	\$1,069
H-4030-M-H04AA	193464	999-001-0096	\$2,462	Stock	\$1,477
H-4030-M-H04AX		999-001-0125	\$2,585	4 Weeks	\$1,551
H-4030-P-H00AA	193465	999-000-9980	\$1,780	Stock	\$1,068
H-4030-P-H00AA-AA		999-001-0130	\$1,838	4 Weeks	\$1,103
H-4030-P-H00AN	193466	999-001-0469	\$1,780	4 Weeks	\$1,068
H-4030-P-H00AX		999-001-0010	\$1,780	4 Weeks	\$1,068
H-4030-P-H00KD	193467	999-001-0023	\$1,880	4 Weeks	\$1,128
H-4030-P-H01AA		Call for P/N	\$2,462	4-6 Weeks	\$1,477
H-4030-P-H04AA	193468	999-001-0098	\$2,462	4 Weeks	\$1,477
H-4030-P-H04AN	6142-02-857	999-001-0428	\$2,474	4-6 Weeks	\$1,485
H4030-P-H04AX		999-001-0147	\$2,585	4 Weeks	\$1,551
H-4030-P-J00AB	6142-01-032	999-001-0198	N/A	Obsolete	N/A
H-4030-P-J04AB	6142-01-028	Call for P/N	N/A	Obsolete	N/A
H-4030/24V	401-34434-20	999-001-0098	\$2,462	4-6 Weeks	\$1,477
H-4030/24V (HSM430B24)		Call for P/N	\$2,462	4-6 Weeks	\$1,477
H-4030/24V-AB	163625	Call for P/N	\$2,462	4-6 Weeks	\$1,477
H-4050	163572	Call for P/N	\$2,042	4 Weeks	\$1,225
H-4050 (HSM460)	401-34435-00	999-000-9974	\$2,042	Stock	\$1,225
H-4050-P-H00AA-AB	193470	Call for P/N	\$2,042	4-6 Weeks	\$1,225
H-4050-P-H00AA	6144-01-802	999-000-9974	\$2,042	Stock	\$1,225
H-4050-P-H00AA-AA		999-001-0117	\$2,126	4 Weeks	\$1,276
H-4050-P-H00AN	193471	999-001-0131	\$2,042	4 Weeks	\$1,225
H-4050-P-H00AX	6144-01-026	999-001-0305	\$2,093	4 Weeks	\$1,256
H-4050-P-H01AA		999-001-0055	\$2,903	4 Weeks	\$1,742
H-4050-P-H01AA-AA		999-001-0157	\$2,987	4 Weeks	\$1,792
H-4050-P-H01AN	6144-02-856	999-001-0322	\$2,903	4 Weeks	\$1,742
H-4050-P-H04AA	193472	999-000-9998	\$2,824	Stock	\$1,694
H-4050-P-H04AA-AA		999-001-0114	\$2,909	4 Weeks	\$1,745
H-4050-P-H04AN	193473	999-001-0347	\$2,825	4 Weeks	\$1,695
H-4050-P-K00AA	195885	Call for P/N	\$2,825	4-6 Weeks	\$1,695
H-4050/24V-AB	401-34435-20	Call for P/N	\$2,861	4-6 Weeks	\$1,717
H-4050/24V (HSM460B24)	163626	999-000-9998	\$2,824	Stock	\$1,694
H-4050/90V	401-34435-90	Call for P/N	\$2,824	4-6 Weeks	\$1,694
H-4075	163573	Call for P/N	\$2,153	4-6 Weeks	\$1,292
H-4075 (HSM490)	401-34436-00	999-000-9985	\$2,153	Stock	\$1,292
H-4075-R-H00AA	193474	999-000-9985	\$2,153	Stock	\$1,292
H-4075-R-H00AA-AA		999-001-0158	\$2,237	4 Weeks	\$1,342
H-4075-R-H00AN	193475	999-000-9989	\$2,153	4-6 Weeks	\$1,292
H-4075-R-H01AA		Call for P/N	\$3,134	4 Weeks	\$1,881
H-4075-R-H04AA	193476	999-000-9996	\$3,134	Stock	\$1,881
H-4075-R-H04AN	193477	999-001-0346	\$3,134	4-6 Weeks	\$1,881
H-4075-R-J00AB		Obsolete	N/A	Obsolete	N/A
H-4075/24V-AB	163627	Call for P/N	\$3,134	4-6 Weeks	\$1,881
H-4075/24V (HSM490-B24)	401-34436-20	999-000-9996	\$3,134	Stock	\$1,881

\*Availability is updated weekly and subject to change. Call to confirm.

\*\*Consult factory for model numbers not listed.

\*\*\*All motors built with original design, documentation, and equipment

<http://www.elwood.com/H-Series.html>

**2017 PRICE LIST: H-SERIES REPLACEMENT MOTORS**

6-INCH FRAME					
Model Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*	Rebuild Price
1326AS-B630F-21		999-001-0139	\$3,575	4 Weeks	\$2,145
1326AS-B630F-21-K6		Call for P/N	\$4,995	4-6 Weeks	\$2,997
1326AS-B660E-21	163575	999-001-0046	\$4,565	4 Weeks	\$2,739
1326AS-B660E-21-A	195736	999-001-0030	\$5,295	4 Weeks	\$3,177
1326AS-B660E-21-K6	163629	999-000-9988	\$5,995	4 Weeks	\$3,597
1326AS-B660F-21-K6		999-001-0091	\$5,995	4 Weeks	\$3,597
1326AS-B690E-21		999-001-0045	\$5,795	4 Weeks	\$3,477
1326AS-B690E-21-K6	163630	999-000-9999	\$6,655	4 Weeks	\$3,993
H-6100	163574	Call for P/N	\$3,095	4-6 Weeks	\$1,857
H-6100 (HSM610)	401-34437-00	Call for P/N	\$3,095	4-6 Weeks	\$1,857
H-6100-Q-H00AA	193478	999-001-0053	\$3,095	4 Weeks	\$1,857
H-6100-Q-H00AA-AA		999-001-0159	\$3,195	4-6 Weeks	\$1,917
H-6100-Q-H01AA		999-001-0128	\$4,995	4-6 Weeks	\$2,997
H-6100-Q-H04AA	193479	999-001-0039	\$4,995	4 Weeks	\$2,997
H-6100-Q-K00AA		999-001-0479	\$3,245	4 Weeks	\$1,758
H-6100-Q-M200AA	195836	N/A	N/A	Obsolete	N/A
H-6100/24V BRK	163628	Call for P/N	\$4,995	4-6 Weeks	\$2,997
H-6100/24VBRK (HSM610B24)	401-34437-20	Call for P/N	\$4,995	4-6 Weeks	\$2,997
H-6200	163575	Call for P/N	\$3,560	4-6 Weeks	\$2,136
H-6200 (HSM620)	401-34438-00	999-000-9992	\$3,560	Stock	\$2,136
H-6200-Q-H00AA	193480	999-000-9992	\$3,560	Stock	\$2,136
H-6200-Q-H-X114	195847	Call for P/N	\$3,560	4-6 Weeks	\$2,136
H-6200-Q-H00AA-AA		999-001-0160	\$3,650	4-6 Weeks	\$2,190
H-6200-Q-H01AA		999-001-0127	\$5,295	4 Weeks	\$3,177
H-6200-Q-H04AA	193481	999-001-0056	\$5,295	4 Weeks	\$3,177
H-6200-Q-H04AA-AA		999-001-0161	\$5,395	4-6 Weeks	\$3,237
H-6200-Q-M200AA	195837	N/A	N/A	Obsolete	N/A
H-6200-Q-S00AX	6166-01-013	N/A	N/A	Obsolete	N/A
H-6200-Q-S04AX	6166-01-008	N/A	N/A	Obsolete	N/A
H-6200/24V BRK	164993	Call for P/N	\$5,295	4-6 Weeks	\$3,177
H-6200/24V BRK	163629	Call for P/N	\$5,295	4-6 Weeks	\$3,177
H-6200/24V BRK (HSM620B24)	401-34438-20	Call for P/N	\$5,295	4-6 Weeks	\$3,177
H-6300	163576	Call for P/N	\$5,595	4-6 Weeks	\$3,357
H-6300 (HSM630)	401-34439-00	999-001-0000	\$5,595	Stock	\$3,357
H-6300-Q-H00AA	193482	999-001-0000	\$5,595	Stock	\$3,357
H-6300-Q-H-X114 (SEE NOTE)	195848	Current Rev is identical to H-6300-Q-H00AA, Use EPN 999-001-0000			
H-6300-Q-H04AA	193483	999-001-0057	\$6,495	4 Weeks	\$3,897
H-6300-Q-H04AA-AA		999-001-0162	\$6,695	4-6 Weeks	\$4,017
H-6300-Q-K00AA	195884	Call for P/N	\$5,695	4-6 Weeks	\$3,417
H-6300-Q-K04AA		999-001-0097	\$6,595	4 Weeks	\$3,957
H-6300-Q-M200AA	195838	N/A	N/A	Obsolete	N/A
H-6300-Q-S00AD	6169-01-012	N/A	N/A	Obsolete	N/A
H-6300-Q-S200AA	195828	N/A	N/A	Obsolete	N/A
H-6300-S-J00AB	6169-01-007	N/A	N/A	Obsolete	N/A
H-6300-S-J00AB	6169-01-008	N/A	N/A	Obsolete	N/A
H-6300/24V BRK	163630	Call for P/N	\$6,495	4-6 Weeks	\$3,897
H-6300/24VBRK (HSM630B24)	401-34439-20	Call for P/N	\$6,495	4-6 Weeks	\$3,897
H-6300/90V (HSM630B90)	401-34439-90	Call for P/N	\$6,495	4-6 Weeks	\$3,897

\*Availability is updated weekly and subject to change. Call to confirm.

\*\*Consult factory for model numbers not listed.

\*\*\*All motors built with original design, documentation, and equipment