

2017 PRICE LIST: 1326AB-SERIES REPLACEMENT MOTORS				
1326AB-B4xxx FRAME SIZE				
Catalog (Model) Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*
1326AB-B410G-21	199156.00	999-001-0677	\$2,327.00	Stock
1326AB-B410G-21-K4	199166.00	999-001-0678	\$3,928.00	4-6 Weeks
1326AB-B410G-21-K4L	199204.00	999-001-0679	\$4,567.00	4 Weeks
1326AB-B410G-21-L	199205.00	999-001-0680	\$2,734.00	4-6 Weeks
1326AB-B410G-M2K4L	199256.00	999-001-0681	\$6,012.00	4-6 Weeks
1326AB-B410G-M2L	199255.00	999-001-0682	\$3,947.00	4-6 Weeks
1326AB-B410G-M2LS	199255.60	999-001-0683	\$3,947.00	4-6 Weeks
1326AB-B410G-S2K4L	199254.00	999-001-0684	\$5,365.00	4-6 Weeks
1326AB-B410G-S2K4LS	199254.60	999-001-0685	\$5,365.00	4-6 Weeks
1326AB-B410G-S2L	199253.00	999-001-0686	\$3,301.00	4-6 Weeks
1326AB-B410G-S2LS	199253.60	999-001-0687	\$3,301.00	4-6 Weeks
1326AB-B410J-21	199181.00	999-001-0688	\$2,677.00	4-6 Weeks
1326AB-B410J-21-K4	199184.00	999-001-0689	\$3,928.00	4-6 Weeks
1326AB-B410J-21-L	199207.00	999-001-0690	\$2,610.00	4-6 Weeks
1326AB-B410J-M2K4L	199260.00	999-001-0691	\$5,642.00	4-6 Weeks
1326AB-B410J-M2L	199259.00	999-001-0692	\$3,947.00	4-6 Weeks
1326AB-B410J-S2L	199257.00	999-001-0693	\$3,301.00	4-6 Weeks
1326AB-B420E-21	199153.00	999-001-0694	\$2,848.00	Stock
1326AB-B420E-21-K4	199163.00	999-001-0695	\$3,976.00	4-6 Weeks
1326AB-B420E-21-K4L	199208.00	999-001-0696	\$4,267.00	4-6 Weeks
1326AB-B420E-21-L	199209.00	999-001-0697	\$3,074.00	4-6 Weeks
1326AB-B420E-21-X92	199231.00	999-001-0698	\$4,956.00	4-6 Weeks
1326AB-B420E-21-X51	199227.00	999-001-0972	\$3,442.00	4-6 Weeks
1326AB-B420E-M2K4L	199264.00	999-001-0699	\$5,695.00	4-6 Weeks
1326AB-B420E-M2K4LS	199264.60	999-001-0700	\$5,695.00	4 Weeks
1326AB-B420E-M2L	199263.00	999-001-0701	\$4,437.00	4-6 Weeks
1326AB-B420E-M2LS	199263.60	999-001-0702	\$4,437.00	4-6 Weeks
1326AB-B420E-S2K4L	199262.00	999-001-0703	\$5,049.00	4-6 Weeks
1326AB-B420E-S2K4LS	199262.60	999-001-0704	\$5,049.00	4-6 Weeks
1326AB-B420E-S2L	199261.00	999-001-0705	\$3,790.00	4-6 Weeks
1326AB-B420E-S2LS	199261.60	999-001-0706	\$3,790.00	4-6 Weeks
1326AB-B420H-21	199182.00	999-001-0707	\$2,971.00	Stock
1326AB-B420H-21-K4	199185.00	999-001-0708	\$4,160.00	4-6 Weeks
1326AB-B420H-21-K4L	199210.00	999-001-0709	\$4,450.00	4-6 Weeks
1326AB-B420H-21-L	199211.00	999-001-0710	\$3,020.00	4-6 Weeks
1326AB-B420H-M2K4L	199268.00	999-001-0711	\$5,889.00	4-6 Weeks
1326AB-B420H-M2K4LS	199268.60	999-001-0712	\$5,889.00	4-6 Weeks
1326AB-B420H-M2L	199267.00	999-001-0713	\$4,235.00	4-6 Weeks
1326AB-B420H-M2LS	199267.60	999-001-0714	\$4,235.00	4-6 Weeks
1326AB-B420H-S2K4L	199266.00	999-001-0715	\$5,242.00	4-6 Weeks
1326AB-B420H-S2K4LS	199266.60	999-001-0716	\$5,242.00	4-6 Weeks
1326AB-B420H-S2L	199265.00	999-001-0717	\$3,589.00	4-6 Weeks
1326AB-B430E-21	199155.00	999-001-0718	\$3,392.00	Stock
1326AB-B430E-21-K4	199165.00	999-001-0719	\$4,299.00	4-6 Weeks
1326AB-B430E-21-K4L	199212.00	999-001-0720	\$4,789.00	4-6 Weeks
1326AB-B430E-21-L	199213.00	999-001-0721	\$3,282.00	4-6 Weeks
1326AB-B430E-21-X93	Obsolete	999-001-0644	Obsolete	Obsolete
1326AB-B430E-M2K4L	199272.00	999-001-0722	\$6,246.00	4-6 Weeks
1326AB-B430E-M2K4LS	199272.60	999-001-0723	\$6,246.00	4-6 Weeks
1326AB-B430E-M2L	199271.00	999-001-0724	\$4,499.00	4-6 Weeks
1326AB-B430E-M2LS	199271.60	999-001-0725	\$4,499.00	4-6 Weeks
1326AB-B430E-S2K4L	199270.00	999-001-0726	\$5,600.00	4-6 Weeks
1326AB-B430E-S2K4LS	199270.60	999-001-0727	\$5,600.00	4-6 Weeks
1326AB-B430E-S2L	199269.00	999-001-0728	\$3,852.00	4-6 Weeks
1326AB-B430E-S2LS	199269.60	999-001-0729	\$3,852.00	4-6 Weeks
1326AB-B430G-21	199183.00	999-001-0730	\$3,392.00	4-6 Weeks
1326AB-B430G-21-K4	199186.00	999-001-0731	\$4,498.00	4-6 Weeks
1326AB-B430G-M2K4L	199276.00	999-001-0732	\$6,298.00	4-6 Weeks
1326AB-B430G-M2L	199275.00	999-001-0733	\$4,494.00	4-6 Weeks
1326AB-B430G-N2LS	199275.60	999-001-1074	\$4,494.00	4-6 Weeks
1326AB-B430G-S2K4L	199274.00	999-001-0734	\$5,652.00	4-6 Weeks
1326AB-B430G-S2K4LS	199274.60	999-001-0735	\$5,652.00	Stock
1326AB-B430G-S2L	199273.00	999-001-0736	\$3,852.00	4-6 Weeks
1326AB-B430G-S2LS	199273.60	999-001-0737	\$3,852.00	4-6 Weeks

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment

2017 PRICE LIST: 1326AB-SERIES REPLACEMENT MOTORS

1326AB-B5xxx FRAME SIZE				
Catalog (Model) Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*
1326AB-B515E-21	199459.00	999-001-0738	\$3,424.00	Stock
1326AB-B515E-21-K5	199473.00	999-001-0739	\$4,948.00	4-6 Weeks
1326AB-B515E-21-K5L	199512.00	999-001-0740	\$5,241.00	4-6 Weeks
1326AB-B515E-21-L	199513.00	999-001-0741	\$3,414.00	4-6 Weeks
1326AB-B515E-21-X51	199531.00	999-001-0742	\$4,234.00	4-6 Weeks
1326AB-B515E-M2K5L	199565.00	999-001-0743	\$6,723.00	4-6 Weeks
1326AB-B515E-M2K5LS	199565.60	999-001-0744	\$6,723.00	4-6 Weeks
1326AB-B515E-M2L	199564.00	999-001-0745	\$5,467.00	4-6 Weeks
1326AB-B515E-M2LS	199564.60	999-001-0746	\$5,467.00	4-6 Weeks
1326AB-B515E-S2K5L	199563.00	999-001-0747	\$6,076.00	4-6 Weeks
1326AB-B515E-S2K5LS	199563.60	999-001-1075	\$6,076.00	4-6 Weeks
1326AB-B515E-S2L	199562.00	999-001-0748	\$4,149.00	4-6 Weeks
1326AB-B515E-S2LS	199562.60	999-001-0749	\$4,149.00	4-6 Weeks
1326AB-B515G-21	199493.00	999-001-0750	\$3,126.00	4-6 Weeks
1326AB-B515G-21-K5	199495.00	999-001-0751	\$4,948.00	4-6 Weeks
1326AB-B515G-21-K5L	199514.00	999-001-0752	\$5,234.00	4-6 Weeks
1326AB-B515G-21-L	199515.00	999-001-0753	\$3,414.00	4-6 Weeks
1326AB-B515G-M2K5L	199569.00	999-001-0754	\$6,715.00	4-6 Weeks
1326AB-B515G-M2K5LS	199569.60	999-001-0755	\$6,715.00	Stock
1326AB-B515G-M2L	199568.00	999-001-0756	\$4,796.00	4-6 Weeks
1326AB-B515G-M2LS	199568.60	999-001-0757	\$4,796.00	4-6 Weeks
1326AB-B515G-S2K5L	199567.00	999-001-0758	\$6,068.00	4-6 Weeks
1326AB-B515G-S2K5LS	199567.60	999-001-0759	\$6,068.00	4-6 Weeks
1326AB-B515G-S2L	199566.00	999-001-0760	\$4,149.00	Stock
1326AB-B515G-S2LS	199566.60	999-001-0761	\$4,149.00	4-6 Weeks
1326AB-B520E-21	199460.00	999-001-0762	\$3,871.00	4-6 Weeks
1326AB-B520E-21-K5	199474.00	999-001-0763	\$5,260.00	4-6 Weeks
1326AB-B520E-21-L	199517.00	999-001-0764	\$3,675.00	4-6 Weeks
1326AB-B520E-M2K5L	199573.00	999-001-0765	\$7,048.00	4-6 Weeks
1326AB-B520E-M2K5LS	199573.60	999-001-0766	\$7,048.00	4-6 Weeks
1326AB-B520E-M2L	199572.00	999-001-0767	\$5,071.00	4-6 Weeks
1326AB-B520E-M2LS	199572.60	999-001-0768	\$5,071.00	4-6 Weeks
1326AB-B520E-S2K5L	199571.00	999-001-0769	\$6,402.00	Stock
1326AB-B520E-S2L	199570.00	999-001-0770	\$4,425.00	4-6 Weeks
1326AB-B520E-S2LS	199570.60	999-001-0771	\$4,425.00	4-6 Weeks
1326AB-B520F-21	199494.00	999-001-0772	\$3,709.00	4-6 Weeks
1326AB-B520F-21-K5	199496.00	999-001-0773	\$5,257.00	Stock
1326AB-B520F-21-K5L	199518.00	999-001-0774	\$5,560.00	4-6 Weeks
1326AB-B520F-21-L	199519.00	999-001-0775	\$3,675.00	4-6 Weeks
1326AB-B520F-M2K5L	199577.00	999-001-0776	\$7,060.00	4-6 Weeks
1326AB-B520F-M2K5LS	199577.60	999-001-0777	\$7,060.00	Stock
1326AB-B520F-M2L	199576.00	999-001-0778	\$5,742.00	4-6 Weeks
1326AB-B520F-M2LS	199576.60	999-001-0779	\$5,742.00	4-6 Weeks
1326AB-B520F-S2K5L	199575.00	999-001-0780	\$6,413.00	4-6 Weeks
1326AB-B520F-S2K5LS	199575.60	999-001-0781	\$6,413.00	4-6 Weeks
1326AB-B520F-S2L	199574.00	999-001-0782	\$5,204.00	4-6 Weeks
1326AB-B520F-S2LS	199574.60	999-001-0783	\$5,204.00	4-6 Weeks
1326AB-B530E-21	199462.00	999-001-0784	\$4,626.00	4 Weeks
1326AB-B530E-21-K5	199476.00	999-001-0785	\$5,987.00	4 Weeks
1326AB-B530E-21-K5L	199520.00	999-001-0786	\$6,558.00	4-6 Weeks
1326AB-B530E-21-L	199521.00	999-001-0787	\$4,915.00	4-6 Weeks
1326AB-B530E-21-X93	199555.00	999-001-0788	\$8,430.00	4-6 Weeks
1326AB-B530E-21-Z06	199535.00	999-001-0977	\$6,141.00	4-6 Weeks
1326AB-B530E-M2K5L	199581.00	999-001-0789	\$8,112.00	4-6 Weeks
1326AB-B530E-M2K5LS	199581.60	999-001-0790	\$8,112.00	4-6 Weeks
1326AB-B530E-M2L	199580.00	999-001-0791	\$7,252.00	4-6 Weeks
1326AB-B530E-M2LS	199580.60	999-001-0792	\$7,252.00	Stock
1326AB-B530E-S2K5L	199579.00	999-001-0793	\$7,466.00	4-6 Weeks
1326AB-B530E-S2K5LS	199579.60	999-001-0794	\$7,466.00	4-6 Weeks
1326AB-B530E-S2L	199578.00	999-001-0795	\$5,732.00	4-6 Weeks
1326AB-B530E-S2LS	199578.60	999-001-0796	\$5,732.00	4-6 Weeks

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment

2017 PRICE LIST: 1326AB-SERIES REPLACEMENT MOTORS				
1326AB-B7xxx FRAME SIZE				
Catalog (Model) Number	Rockwell P/N	Elwood P/N	List Price	New Motor Availability*
1326AB-B720E-21	199760.00	999-001-0797	\$5,733.00	4-6 Weeks
1326AB-B720E-21-K7	199774.00	999-001-0798	\$7,274.00	4-6 Weeks
1326AB-B720E-21-K7L	199794.00	999-001-0799	\$6,948.00	4-6 Weeks
1326AB-B720E-21-L	199795.00	999-001-0800	\$6,029.00	4-6 Weeks
1326AB-B720E-M2K7L	199844.00	999-001-0801	\$8,523.00	4-6 Weeks
1326AB-B720E-M2K7LS	199844.60	999-001-0802	\$8,523.00	4-6 Weeks
1326AB-B720E-M2L	199843.00	999-001-0803	\$7,554.00	Stock
1326AB-B720E-M2LS	199843.60	999-001-0804	\$7,554.00	4-6 Weeks
1326AB-B720E-S2K7L	199842.00	999-001-0805	\$7,877.00	Stock
1326AB-B720E-S2L	199841.00	999-001-0806	\$6,605.00	4 Weeks
1326AB-B720E-S2LS	199841.60	999-001-0807	\$6,605.00	Stock
1326AB-B720F-21	199805.00	999-001-0808	\$6,234.00	4-6 Weeks
1326AB-B720F-21-K7	199831.00	999-001-1003	\$7,274.00	4-6 Weeks
1326AB-B720F-M2K7L	199861.00	999-001-0809	\$9,418.00	4-6 Weeks
1326AB-B720F-M2K7LS	199861.60	999-001-0810	\$9,418.00	4-6 Weeks
1326AB-B720F-M2L	199856.00	999-001-0811	\$7,794.00	4-6 Weeks
1326AB-B720F-M2LS	199856.60	999-001-0812	\$7,794.00	4-6 Weeks
1326AB-B720F-S2K7L	199860.00	999-001-0813	\$8,771.00	4-6 Weeks
1326AB-B720F-S2L	199859.00	999-001-0814	\$7,147.00	4-6 Weeks
1326AB-B720F-S2LS	199859.60	999-001-0815	\$7,147.00	Stock
1326AB-B730E-21	199762.00	999-001-0816	\$7,392.00	4-6 Weeks
1326AB-B730E-21-K7	199776.00	999-001-0817	\$8,645.00	4-6 Weeks
1326AB-B730E-M2K7L	199848.00	999-001-0818	\$10,829.00	4-6 Weeks
1326AB-B730E-M2K7LS	199848.60	999-001-0819	\$10,829.00	4-6 Weeks
1326AB-B730E-M2L	199847.00	999-001-0820	\$8,992.00	4-6 Weeks
1326AB-B730E-M2LS	199847.60	999-001-0821	\$8,992.00	4-6 Weeks
1326AB-B730E-S2K7L	199846.00	999-001-0822	\$9,981.00	4-6 Weeks
1326AB-B730E-S2L	199845.00	999-001-0823	\$8,344.00	4-6 Weeks
1326AB-B730E-S2LS	199845.60	999-001-0824	\$8,344.00	4-6 Weeks
1326AB-B730E-X113	199858.00	999-001-0999	\$10,175.00	4-6 Weeks
1326AB-B740C-21	199757.00	999-001-0825	\$7,746.00	4-6 Weeks
1326AB-B740C-21-K7	199771.00	999-001-0826	\$9,299.00	4-6 Weeks
1326AB-B740C-M2K7L	199852.00	999-001-0827	\$11,317.00	4-6 Weeks
1326AB-B740C-M2L	199851.00	999-001-0828	\$10,514.00	4-6 Weeks
1326AB-B740C-M2LS	199851.60	999-001-0829	\$10,514.00	4-6 Weeks
1326AB-B740C-S2L	199849.00	999-001-0830	\$9,868.00	4-6 Weeks
1326AB-B740C-S2LS	199849.60	999-001-0831	\$9,868.00	4-6 Weeks
1326AB-B740E-21	199764.00	999-001-0832	\$8,539.00	4-6 Weeks
1326AB-B740E-21-K7	199778.00	999-001-0833	\$10,100.00	4-6 Weeks
1326AB-B740E-21-L	199834.00	999-001-0975	\$8,848.00	4-6 Weeks
1326AB-B740E-M2K7L	199864.00	999-001-0834	\$11,872.00	4-6 Weeks
1326AB-B740E-M2K7LS	199864.60	999-001-0835	\$11,872.00	4-6 Weeks
1326AB-B740E-M2L	199854.00	999-001-0836	\$10,227.00	4-6 Weeks
1326AB-B740E-M2LS	199854.60	999-001-0837	\$10,227.00	Stock
1326AB-B740E-S2K7L	199863.00	999-001-0838	\$11,225.00	4-6 Weeks
1326AB-B740E-S2L	199862.00	999-001-0839	\$9,579.00	4-6 Weeks
1326AB-B740E-S2LS	199862.60	999-001-0840	\$9,579.00	4-6 Weeks

*Availability is updated weekly and subject to change. Call to confirm.

**Consult factory for model numbers not listed.

***All motors built with original design, documentation, and equipment