



	HARTING Product Termination Notification	PTN
---	---	------------

Business Unit: *Electronics* PTN/Cable/14/40/ABCD
Product range: *har-speed M12 cable assemblies* Date: 2014-05-09

Title: *har-speed M12 x-coded overmoulded cable assemblies*

Details of product termination

1. Concerned part number (see also attachment):		
<ul style="list-style-type: none"> - 21 03 483 18XX - 21 03 483 58XX 		
2. Reason for termination:		
<p>The existing 2103 881 5805 has no technical benefit versus recently launched har-speed M12 Slim Design Crimp 2103 881 1805. Due to the size of the connector the acceptance on the market is still very low. The tool for the housing is damaged!</p>		
3. Possible replacement products		
<p>We have following possible replacement for the overmoulded products:</p> <table style="width: 100%; border: none;"> <tr> <td style="width: 50%; vertical-align: top;"> <p>OLD part numbers:</p> <p>21 03 483 18XX 21 03 483 58XX</p> </td> <td style="width: 50%; vertical-align: top;"> <p>NEW part numbrs</p> <p>21 33 01 00 850 XXX 21 33 01 01 850 XXX</p> </td> </tr> </table> <div style="display: flex; justify-content: space-around; align-items: center; margin-top: 20px;">   </div> <p>Please note that the alternative is not overmoulded!</p>	<p>OLD part numbers:</p> <p>21 03 483 18XX 21 03 483 58XX</p>	<p>NEW part numbrs</p> <p>21 33 01 00 850 XXX 21 33 01 01 850 XXX</p>
<p>OLD part numbers:</p> <p>21 03 483 18XX 21 03 483 58XX</p>	<p>NEW part numbrs</p> <p>21 33 01 00 850 XXX 21 33 01 01 850 XXX</p>	
4. Scheduled date of:		
<ol style="list-style-type: none"> 1. <i>Last order: non disposable in SAP!</i> 2. <i>Last delivery: has taken place!</i> 		
5. Data sheet (optional):		
<ul style="list-style-type: none"> • TB_21330101850XXX 		