

# 產品變更通知 PRODUCT CHANGE NOTIFICATION

PCN No.	IC-PPCN-150906	Issue Date	2015-11-16
TITLE	SOD系列印字方向變更 (Marking Printing Change	列印字方向變更 (Marking Printing Change of SOD	
	series)		

### <u>變更主旨(TITLE):</u>

SOD 系列封裝,印字方向變更。

SOD series printing direction change.

#### 變更類別(CHANGE TYPE):

Design	Process	□Raw Material		cturing Site
Testing	☐Packing/Shippi	ing/Labeling	■Other _	Marking Change

## 變更說明(DESCRIPTION OF CHANGE):

 本公司 SOD 系列封裝之印字原以負端在右邊為正印,為配合業界規則及利於客戶使用,故 予以變更統一為負端在左邊為正印。如下說明:

UTC is going to change the marking of negative terminal from right side to left side in order to comply with industry rules. Detail is as below:

PACKAGE	Marking Code	原印字(Current Marking)	變更後(New Marking)
SOD-123 SOD-323 SOD-523	4148G:產品代碼 (Product code)	A 4148G K	<b>K</b> 4148G A

#### 品質驗證(VERIFICATION/QUALIFICATION):

不影響原有品質及規格。


No change to electrical specification, quality or reliability in the final product.

## 變更識別(IDENTIFICATION METHOD TO DISTINGUISH CHANGE)

本公司自 2016/1/1 起可供應新產品,現有庫存品繼續出貨至用罄後全面供應,實際交貨依客戶之要求,但同批出貨採單一規格,禁止混裝。

Product shipments using this change will begin on Jan-1-2016. Timing of shipment of the changed part will vary depending on customer demand and inventory levels. Currently both of old and new tube type will be delivered for the time being. And one shipment one tube type only to be allowed.





# 產品變更通知 PRODUCT CHANGE NOTIFICATION

PCN No.	IC-PPCN-150906	Issue Date	2015-11-16
TITLE	OD系列印字方向變更 (Marking Printing Change of SOD		Page 2 of 2
	series)		

### <u>生效日期(COMPLETE DATE):</u>

- 1. 2016-02-16
- 若 貴公司未於收到本通知書起30日內,另以書面提出要求,本公司將視同 貴公司已 同意本項變更。

UTC will consider this change approved unless specific requests are addressed in writing within 30 days of receipt of this PCN.

#### 適用範圍(APPLICABLE PRODUCTS):

SOD-123, SOD-323 and SOD-523 packages.

Product Name	SOD-123	SOD-323	SOD-523
1N4148	V V	✓ ✓	V V
1N5819	· ·	,	,
1SS355	,	<b>√</b>	
BAT54TS			<b>/</b>
BAT54WS		<b>√</b>	
BAV20W	✓	<b>√</b>	
BB178			<b>✓</b>
BB179			<b>✓</b>
BZT52BXXXS	✓	<b>√</b>	
BZT52CXXXS		✓	
MBR0530	✓	✓	
MBR0540	✓	✓	✓
MBR0560	✓		
RB160M-60	✓		
RB501V-40		✓	
RB520S30			✓
RB521S30			✓
RB751V40		✓	✓
SD103AW	✓		✓
SD103AWS		✓	
SD106WS	✓	✓	
USNB053	✓		
UUDZ 12B		✓	
ZD1.8 THRU ZD36	✓	✓	

友順對此變更所引起之不便表達致歉,如果對本變更有任何問題,請與我們的業務代表或經銷 商聯絡。

We apologize for any inconvenience causing from this change, If you have any questions concerning this change, please contact your local sales or UTC's sales representative.

