

These connectors are manufactured with the red spacer assembled in the **pre-latch position**. Refer to Figure 1, Detail A. Shipping and handling may displace the connectors to the **full-lock position**, as shown in Figure 1, Detail B.




Figure 1

To once again return the connectors to the **pre-latch position**, insert Extraction Tool 3-1579007-6 (or a small jewelers screwdriver) into the small slot on the edge in the center of the red spacer. Rotate the tool toward the front of connector to disengage the spacer and return it to the **pre-latch position**. See Figure 2.




Figure 2

Revision Summary:
New release of 408-10128